

BK-1 (TYPE A-1) (Overall completion 91.30 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – External texture paint in progress & surface dressing for PCC at stilt floor.



BK-2 (TYPE A-1) (Overall completion 75.10 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – External plaster of common area and brick work of Garbage shaft.



BK-3 (TYPE A-1) (Overall completion 63.30 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – Brick work of parapet wall and railing fixing at podium.



BK-4 (TYPE A-1) (Overall completion 62.82 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – Fixing of railing in balconies.



BK-5 (TYPE A-2) (Overall completion 67.39 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – External plaster of flat 2, Casting of terrace floor column, internal plaster in corridor.



BK-6 (TYPE A-2) (Overall completion 84.61%)

Total Floor – Stilt + 10

Total flat = 60

Progress – Plaster repairing work and Kota stone fixing on big podium.



BK-7 (TYPE B-1) (Overall completion 84.61 %)

Total Floor – Stilt + 11

Total flat = 119

Progress – External plaster, wall tiles fixing in toilets, Granite fixing on lift fascia, Green marble fixing in staircase, brick work of meter room at stilt floor.



BK-8 (TYPE B-1 & TYPE B2) (Overall completion 86.60 %)

Total Floor – Stilt + 11

Total flat = 33

Progress – Matt finish tiles fixing in balconies and brick work of partition wall in kitchen.



COMMUNITY CENTRE - (Overall completion 86.60 %)

Total floor – Basement +03

Progress – No progress.



FACILITY BLOCK - (Overall completion 95.15%)

Total floor – Ground +01

Progress – No progress.



Gate No. 1 - (Overall completion 90.00 %)

Progress – No progress.



Swimming pool - (Overall completion 05.00 %)

Progress -PCC of swimming pool done, RCC work of Filtration plant/Balancing tank of swimming pool in progress.



STP - (Overall completion 37.26 %)

Progress – Water proofing of top slab in progress.



Power house - (Overall completion 96.00 %)

Progress – Generators, transformers, HT/LT cables and control panels procured, Awaiting Energising.