
- 1. All Common areas and amenities are ready for handing over to the Society.
- 2. Till date a total of 217 DUs out of 256 (Officer Block-110 and Sailor Block-107) have been handed over to the allottees.
- 3. Conveyance deed executed in respect of 136 DUs.
- 4. Installation of **Electricity Check Meter** in domestic Transformer was completed.
- 5. Approx 5 family already moved in the project.



TOWER NO: A OFFICERS (Overall completion-99.99%)

Total floors: S1+S2+8



TOWER NO: B OFFICERS (Overall completion-99.99%)

Total floors: S1+S2+8



TOWER NO: C OFFICERS (Overall completion-99.99%)

Total floors: S1+S2+8



TOWER NO: D OFFICERS (Overall completion-99.99%)

Total floors: S1+S2+8



TOWER NO: E SAILOR (Overall completion-99.96%)

Total floors: S1+S2+11



TOWER NO: F SAILOR (Overall completion-99.95%)

Total floors: \$1+\$2+11



TOWER NO: G SAILOR (Overall completion-99.99%)

Total floors: \$1+\$2+11



TOWER NO: COMMUNITY CENTER (Overall completion-99.00%)

Total floors: G+1


PROGRESS:

FIRE FIGHTING WORK - 97% completed -100% completed

PAINTING - 100% (1st coat paint completed)

ELECTRICAL WORK - 95 completed
DOOR & WINDOW FIXING - 60% completed
TILING - 95% completed
BRICK WORK - 100% completed

SWIMMING POOL



SWIMMING POOL- (Overall completion- 98%)

PROGRESS: - Mosaic Tile Work completed.

- Deck area tiling work also completed.

LAND SCAPING WORK AT SITE











PAVER BLOCK FIXING



EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)



EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 99%)

All works completed. Common load charging completed. **PROGRESS**:

EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)







EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 99%)

PROGRESS:

CIVIL FOUNDATIONS - 100% completed **EQUIPMENT ERECTION** - 100% completed - FP & TP erected STRUCTURE ERECTION **CABLE LAYING** - 100% completed **CABLE END TERMINATION** - 99% completed - 100% Completed **LT PANEL** - 100% Completed) LIGHTNING ARRESTOR - 99% Completed STREET LIGHT - 99% Completed **TELEPHONE SYSTEM** -IR TEST completed **TESTING**