1. **External Development Work :** All external development works completed

2. Lift Work: Commissioning of Lifts in all 07 blocks completed.

3. **<u>Swimming Pool</u>**: All civil works completed, Fixing of light and commissioning is in progress.

4. **<u>STP</u>**: All works completed including testing and commissioning

5. **<u>Towers</u>**: All major works in the towers are completed. Testing and commissioning of services are in progress.

6. Energization of Sub Station: Work completed and Sub Stations energized.

7. <u>Status of Completion/Occupancy Certificate</u>: Application for OC/CC submitted to BDA with EDC of end Dec 18.

8. **Possession & Registration of DUs:** Handing over of DUs commenced w.e.f 18 May 18 and 72 Dus(Officer Block-54 and Sailor Block-18) handed over. Registration of DUs commenced with 26 DUs(Officer Block-20 and Sailor Block-6) already registered.



<u>TOWER NO</u>: A OFFICERS (Overall completion-99.8%)

Total floors:S1+S2+8Total Flats:32

PROGRESS:

FIRE FIGHTING WORK EXTERNAL PAINT INTERNAL PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING SANITARY FITTING CP FITTING

- 99% completed

- 100% completed
- 100% (Final paint completed)
- 100% completed
- 100% completed
- 100% completed
- 100% completed



TOWER NO: B OFFICERS (Overall completion-99.8%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS:

FIRE FIGHTING WORK EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING SANITARY FITTINGS PLUMBING

-99% completed

-100% completed - 100% completed - 100% completed - 100% completed

- 100% completed



TOWER NO:

Total floors: S1+S2+8 Total Flats: 32

PROGRESS:

FIRE FIGHTING WORK **EXTERNAL PAINT** ELECTRICAL WORK **DOOR & WINDOW FIXING** SANITARY FITTING PLUMBING

- 99% completed

- -100% completed
- 100% completed
- 100% completed
- 100% completed
- 100% completed



TOWER NO: D OFFICERS (Overall completion-99.8%)

Total floors: S1+S2+8 Total Flats: 32

PROGRESS:

FIRE FIGHTING WORK EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING SANITARY FITTING CP FITTING 99% completed
100% completed
100% completed
100% completed
100% completed
100% completed



TOWER NO: E SAILOR (Overall completion-99.6%)

Total floors:S1+S2+11Total Flats:43

PROGRESS:

FIRE FIGHTING WORK EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING SANITARY FITTING PLUMBING

- 99% completed

- 100% completed
- 100% completed
- 100% completed
- -100% completed
- 100% completed



TOWER NO: F SAILOR (Overall completion-99.25%)

Total floors:S1+S2+11Total Flats:43

PROGRESS:

FIRE FIGHTING WORK EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING STAIRCASE RAILING FALSE CEILING TILING PLUMBING

-99% completed

-100% completed

- 100% completed
- 100% completed
- -100% completed
- -100% Completed
- 100% completed
- 100% completed



TOWER NO: G SAILOR (Overall completion-99.8%)

Total floors:S1+S2+11Total Flats:42

PROGRESS:

FIRE FIGHTING WORK EXTERNAL PAINT ELECTRICAL WORK SANITARY FITTING CP FITTING

- 97% completed
- 100% completed
- 100% completed
- 100% completed
- 100% completed



TOWER NO: COMMUNITY CENTER (Overall completion-97.80%)


Total floors: G+1

PROGRESS:

FIRE FIGHTING WORK EXTERNAL PAINT PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING TILING BRICK WORK

- 97% completed
- -85% completed
- 100% (1st coat paint completed)
- 95 completed
- 60% completed
- 80% completed
- 100% completed

SWIMMING POOL



SWIMMING POOL- (Overall completion- 95%)

PROGRESS: - Mosaic Tile Work completed.

- Deck area tiling work also completed.

LAND SCAPING WORK AT SITE





PAVER BLOCK FIXING



SIGNAGE BOARD FIXING





EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)




EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 99%)

PROGRESS: All works completed. Common load charging completed.

EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)







EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 99%)

PROGRESS:

CIVIL FOUNDATIONS EQUIPMENT ERECTION STRUCTURE ERECTION CABLE LAYING CABLE END TERMINATION LT PANEL LIGHTNING ARRESTOR STREET LIGHT TELEPHONE SYSTEM TESTING 100% completed
100% completed
FP & TP erected
100% completed
99% completed
100% Completed)
99% Completed
99% Completed
99% Completed
IR TEST completed