
PROGRESS JAIPUR AS ON 15 SEPTEMBER 19

TOWER-C: 7th FLOOR SLAB




- Brick work at 5th floor in Progress.
 GI conduit work at 1st floor.
 6th floor columns RCC work in progress.
 Basement brick work and Firefighting work in progress.

TOWER- D: TERRACE FLOOR SLAB




- Plumbing work at 9th floor and Electrical work 7th& 8th floor in Progress. Doors frame fixing work at 10th floor and Plaster work at 5th floor in Progress. Terrace floor work in Progress.
- 3.

TOWER- E: TERRACE BRICK BATS COBA



- 1. Electric & Plumbing work at 10th floor in Progress.
- 2. Electrical wiring & Water proofing work in progress.
- 3. External plaster work &Tile & marble flooring work in progress.
- 4. Door shutters & Upvc doors, windows fixing work in progress
- 5. Terrace floor brick bats coba & other work in progress.

TOWER-F: TERRACE FLOOR SLAB




- 1.
- Terrace floor work &Electric work at 10th floor in Progress.

 Plumbing work at 10th floor & Internal Plaster work at 10th floor in Progress.


 Water proofing work in progress in toilets & balconies &10th floor electrical wiring work 2.
- 3. in progress.
- Primer painting & putty base coat work at 9th& 10th floor & Tile flooring work at 10th floor in progress.
- 5. Machine room shuttering & reinforcement work
- 6. OHWT Rcc work in progress.
- Door shutters & Upvc doors, windows fixing work in progress.
- Terrace floor brickbats coba & other work in progress.

TOWER- L: TERRACE FLOOR SLAB



- 1. Brick work at 9th floor & Terrace floor work in progress.
- Electrical and Plaster work at 1st & bull mark, chicken wire mesh at 2nd floor.
 Door frame fixing at 1st and 2nd floor Plumbing work in Progress.
- 4. Firefighting work in progress in basement.
- 5. Plumbing work 5th floor in progress.

TOWER-H:TERRACE FLOOR SLAB




- 9th floor Plumbing and Electrical work at 7th floor in Progress.
 Parapet wall brick work & door frame fixing work in Progress 6th floor.
 Water proofing & firefighting work in progress in basement.

TOWER- J: TERRACE FLOOR SLAB



- Plumbing work at 8th floor & electrical work at 4th floor in Progress.
 Door frame fixing at 5th floor & terrace floor work in progress.
- 3. Basement firefighting & brick work in progress.
- Water proofing work in progress.

NON TOWER



- Stitching slab RCC work in progress.
 Shuttering, Reinforcement work of footings &RCC of retaining wall in Progress.
 Under ground water tank RCC work in progress.
 Non tower part -4,3 & 6 slab RCC work in progress
 Non tower part -5 columns & retaining wall RCC work in progress.
 STP excavation work in progress.

BOUNDARY WALL

PROGRESS:

- 1. R.R.M & plinth Beam RCC work in progress.
- 2. Precast panal & columns fixing work in progress.
- 3. MS angle fixing work in progress.
- 4. Gate -2 RCC brickwork & Gate -1 Excavation & PCC work in progress.
- 5. Earthwork, Disposal & Compacting Earth works in progress.

EXTERNAL SEWAGE

PROGRESS:

- 1. Excavation work of sewer & water storm line in progress.
- 2. Sewer pipe line & manholes making work in progress.
- 3. Sewer line manholes making work in progress.

COMMUNITY CENTRE



- 1. OHWT RCC& brick work in progress at terrace floor.
- 2. Electrical work ground& Plumbing work in basement floor in progress.
- 3. External plaster work in progress.