## **TOWER-1A: TERRACE FLOOR SLAB**




TOWER NO: 1A (Overall completion 72.90%)

Total Floors: - Stilt + 12 Upper floors

Total Flats: - 24 (Duplex Type-A1)

- 1. Structural works up to terrace floor slab completed.
- 2. 12<sup>th</sup> floor concrete block masonry work completed & terrace floor parapet wall block masonry work completed.
- 3. Staircase headroom column concrete work completed and head room slab completed, lift machine room and OHT work in progress.
- 4. 12<sup>th</sup> floor internal wall and ceiling plastering work completed.
- 5. Door frame fixing work completed upto 4<sup>th</sup> floor.
- 6. 12<sup>th</sup> floor internal waterproofing work completed.
- 7. Tiling work completed upto 5<sup>th</sup> floor, 6<sup>th</sup> floor in progress.
- 8. 3<sup>rd</sup> & 4<sup>th</sup>floor toilet flooring and wall dadoing work in progress.
- 9. 10<sup>th</sup>floor Balcony railing work completed.
- 10. Internal staircase railing completed upto 12<sup>th</sup> floor.
- 11. 12<sup>th</sup> floor internal wall electrical conduiting work completed.
- 12. Internal plumbing work (CPVC) and (SWR PVC) pipe work completed upto 12<sup>th</sup> floor.
- 13. External plastering work (South, East, West, North side) in progress.
- 14. 1<sup>st</sup> to 4<sup>th</sup> floor door shutter fixing work in progress.

# **TOWER-1B: TERRACE FLOOR SLAB**



TOWER NO: 1B (Overall completion 72.90%)

Total Floors: - 2 Stilts + 12 Upper floors

Total Flats: - 24 (Duplex Type-A1)

- 1. Structural works up to Terrace floor slab completed. Lift machine room and OHT in progress.
- 2. Terrace floor parapet wall block masonry work completed.
- 3. Concrete block masonry work completed upto 12th floor.
- 4. 12<sup>th</sup> floor internal wall and ceiling plastering work completed.
- 5. 8<sup>th</sup> floor Tiling work in progress.
- 6. 7<sup>th</sup> & 8<sup>th</sup> floor Door frame fixing work in progress.
- 7. Balcony railing work completed upto 8<sup>th</sup> floor.
- 8. Internal staircase railing work completed upto 6<sup>th</sup> floor. 7<sup>th</sup> and 8<sup>th</sup> floor work in progress.
- 9. 1<sup>st</sup> & 2<sup>nd</sup> floor internal staircase cuddapah stone work in progress.
- 10. 12<sup>th</sup> floor internal waterproofing work completed.
- 11. Internal wall electrical conduiting work completed upto 12<sup>th</sup> floor.
- 12. Internal plumbing (CPVC) work completed upto 12<sup>th</sup> floor, and internal (SWR PVC) pipe work completed upto 12<sup>th</sup> floor.
- 13. External plastering work (South, east, and west side) in progress.
- 14. 3<sup>rd</sup> floor toilet wall dadoing work in progress.
- 15. 1<sup>st</sup> floor door shutter fixing work in progress.
- 16. 1<sup>st</sup> to 4<sup>th</sup> floor internal wall putty work in progress.

# TOWER-1C: TERRACE FLOOR SLAB



TOWER NO: 1C (Overall completion 66.10%)

Total Floors: - Stilt + 12 Upper floors

Total Flats: - 24 (Duplex Type-A1)

- 1. Structural work upto 12<sup>th</sup> floor slab concrete work completed & 12<sup>th</sup> floor roof half slab beam shuttering work(south side) in progress,12<sup>th</sup> floor column concrete work (north side) completed
- 2. 11<sup>th</sup> floor concrete block masonry work completed.
- 3. 9<sup>th</sup> & 10<sup>th</sup> floor internal wall plastering work in progress
- 4. Tiling work completed upto 4<sup>th</sup> floor, 5<sup>th</sup> floor in progress, 4<sup>th</sup> floor toilet dadoing work in progress.
- 5. 1<sup>st</sup> & 2<sup>nd</sup> floor internal staircase cuddapah stone work in progress.
- 6. 7<sup>th</sup> floor internal waterproofing work in progress.
- 7. 3<sup>rd</sup> & 4<sup>th</sup> floor door frame fixing work in progress
- 8. 10<sup>th</sup> floor Balcony railing work in progress.
- 9. Internal Staircase railing work completed upto 6<sup>th</sup> floor, 7th floor in progress.
- 10. 10<sup>th</sup> floor internal wall electrical conduiting work in progress.
- 11. 10<sup>th</sup> floor internal plumbing (CPVC) work completed, 6<sup>th</sup> floor (SWR PVC) pipe work completed.
- 12. External plastering work (Southside) in progress.
- 13. Internal wall putty work (First and second floor) in progress.

# TOWER-2B: TERRACE FLOOR SLAB



TOWER NO: 2B (Overall completion 62.30%)

Total Floors: - 2 Stilts + 12 Upper floors

Total Flats: - 48 (Simplex Type-A2)

- 1. Structural works completed upto terrace floor.
- 2. Staircase headroom slab completed. Lift machine room and OHT shuttering and Bar bending work in progress.
- 3. Concrete block masonry work completed upto 12<sup>th</sup> floor and terrace floor parapet wall block masonry work completed.
- 4. 10<sup>th</sup> & 11<sup>th</sup> floor internal plastering work in progress.
- 5. 6<sup>th</sup> floor Tiling work in progress, 3<sup>rd</sup> & 4<sup>th</sup> floor toilet wall dadoing work in progress.
- 6. Balcony railing work upto 10<sup>th</sup> floor completed.
- 7. Door frame fixing work completed upto 6<sup>th</sup> floor, 7th floor in progress.
- 8. 10<sup>th</sup> floor internal wall electrical conduiting work completed.
- 9. Internal plumbing (CPVC) work completed upto 12<sup>th</sup> floor, 7<sup>th</sup> floor Internal (SWR PVC) pipe work completed.
- 10. Internal wall putty work (second, third, fourth floor) in progress.
- 11. Door shutters upto 5<sup>th</sup> floor fixing work in progress.

# **TOWER-2C: TERRACE FLOOR SLAB**



TOWER NO: 2C (Overall completion 60.20%)

Total Floors: - Stilt + 12 Upper floor

Total Flats: - 48 (Simplex Type-A2)

- 1. Structural work completed upto terrace floor.
- 2. Staircase head room slab completed. Lift machine room and OHT shuttering and Bar bending work in progress.
- 3. 11<sup>th</sup> floor concrete block masonry work in progress.
- 4. 5<sup>th</sup> floor Tiling work in progress, 3<sup>rd</sup> floor toilet wall dadoing work in progress.
- 5. Internal waterproofing work completed upto 10<sup>th</sup> floor.
- 6. Balcony railing work completed upto 10<sup>th</sup> floor.
- 7. 7<sup>th</sup> floor door frame fixing work in progress.
- 8. 10<sup>th</sup> floor internal wall electrical conduiting work in progress.
- 9. 10<sup>th</sup> floor internal plumbing (CPVC) work completed, 10<sup>th</sup> floor (SWR PVC) pipe work in progress.
- 10. 1<sup>st</sup> and 2<sup>nd</sup> floor door shutters fixing work in progress.
- 11. 9<sup>th</sup> and 10<sup>th</sup> floor internal wall and ceiling plastering work in progress.

# **BLOCK-3: SUB STRUCTURE**



BLOCK NO: 3 (Overall completion 13.00%)

Total Floors: - Stilt + 3 Upper floor

Amenities: - Club House & Swimming Pool

- 1. Function hall entrance columns concrete work completed.
- 2. Retaining wall waterproofing work in progress.
- 3. Back filling work in progress.
- 4. Swimming pool area retaining wall shuttering work in progress.
- 5. Plinth beam reinforcement and shuttering work in progress.

## **BLOCK-5: TERRACE FLOOR SLAB**



BLOCK NO: 5 (Overall completion 73.10%)

Total Floors: - Stilt + 10 Upper floors

Total Flats: - 40 (Simplex Type B-II)

- 1. Structural works up to terrace floor slab completed.
- 2. Staircase head room shuttering and bar bending work and lift machine room concrete work in progress.
- 3. Concrete block masonry work completed upto 10th floor & Terrace floor parapet wall block masonry work completed.
- 4. 10<sup>th</sup> floor internal wall plastering work completed.
- 5. 10<sup>th</sup> floor ceiling plastering work completed.
- 6. 5<sup>th</sup> floor tiling work in progress, 5<sup>th</sup> floor toilet wall dadoing work in progress.
- 7. Balcony railing work completed upto 10<sup>th</sup> floor.
- 8. Water proofing work completed upto 10<sup>th</sup> floor.
- 9. 10<sup>th</sup> floor door frame fixing work in progress.
- **10. 10<sup>th</sup> floor internal wall electrical conduiting work completed.**
- 11. 10<sup>th</sup> floor internal plumbing (CPVC) work completed, 10<sup>th</sup> floor (SWR PVC) pipe work completed.
- 12. External plastering work (North side, Westside, Eastside, and Southside) in progress.
- 13. 1<sup>st</sup> to 5<sup>th</sup> floor door shutter fixing work in progress.
- 14. 1<sup>st</sup> to 5<sup>th</sup> floor internal wall putty work in progress.