- 1. External Development Work: All external development works completed
- 2. <u>Lift Work</u>: Commissioning of Lifts in all the 07 blocks completed.
- 3. **Swimming Pool:** All civil works completed, Fixing of lights and commissioning are in progress.
- 4. **STP**: All works completed including testing and commissioning
- 5. <u>Towers</u>: All major works in the towers are completed. Testing and commissioning of services are in progress.
- 6. **Energization of Sub- Station: Work completed and Sub-station energized.**
- 7. Status of Completion/Occupancy Certificate: OC has been received from BDA on 27 Nov 18.
- 8. <u>Possession & Registration of DUs:</u> Total of 99 DUs (Officer Block-69 and Sailor Block-30) have been handed over out of 254 DUs. Registration completed for 44 DUs.
- 9. All Common areas and amenities are ready for handing over to the Society.



TOWER NO: A OFFICERS (Overall completion-99.99%)

Total floors: S1+S2+8 Total Flats: 32

PROGRESS:

FIRE FIGHTING WORK - 100% completed - 100% completed

INTERNAL PAINTING - 100% (Final paint completed)

ELECTRICAL WORK - 100% completed
DOOR & WINDOW FIXING - 100% completed
SANITARY FITTING - 100% completed
CP FITTING - 100% completed



TOWER NO: B OFFICERS (Overall completion-99.99%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS:

FIRE FIGHTING WORK

EXTERNAL PAINT

ELECTRICAL WORK

DOOR & WINDOW FIXING

SANITARY FITTINGS

-100% completed

-100% completed

-100% completed

-100% completed

-100% completed

-100% completed



TOWER NO: C OFFICERS (Overall completion-99.99%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS:

FIRE FIGHTING WORK

EXTERNAL PAINT

ELECTRICAL WORK

DOOR & WINDOW FIXING

SANITARY FITTING

PLUMBING

- 100% completed
- 100% completed
- 100% completed
- 100% completed



TOWER NO: D OFFICERS (Overall completion-99.99%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS:

FIRE FIGHTING WORK

EXTERNAL PAINT

ELECTRICAL WORK

DOOR & WINDOW FIXING

SANITARY FITTING

CP FITTING

- 100% completed
- 100% completed
- 100% completed
- 100% completed



TOWER NO: E SAILOR (Overall completion-99.96%)

Total floors: \$1+\$2+11

Total Flats: 43

PROGRESS:

FIRE FIGHTING WORK

EXTERNAL PAINT


ELECTRICAL WORK

DOOR & WINDOW FIXING

SANITARY FITTING

PLUMBING

- 100% completed
-100% completed
-100% completed
-100% completed



TOWER NO: F SAILOR (Overall completion-99.90%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: FIRE FIGHTING WORK -100% completed

EXTERNAL PAINT
-100% completed
- 100% completed



TOWER NO: G SAILOR (Overall completion-99.99%)

Total floors: \$1+\$2+11

Total Flats: 42

PROGRESS:

FIRE FIGHTING WORK

EXTERNAL PAINT

- 100% completed



TOWER NO: COMMUNITY CENTER (Overall completion-98.80%)

Total floors: G+1

PROGRESS:

FIRE FIGHTING WORK - 97% completed EXTERNAL PAINT -100% completed

PAINTING - 100% (1st coat paint completed)

ELECTRICAL WORK - 95 completed
DOOR & WINDOW FIXING - 60% completed
TILING - 80% completed
BRICK WORK - 100% completed

SWIMMING POOL



SWIMMING POOL- (Overall completion- 95%)

 $\underline{\textbf{PROGRESS:}} \textbf{ -} \textbf{ Mosaic Tile Work completed.}$

- Deck area tiling work also completed.

LAND SCAPING WORK AT SITE











PAVER BLOCK FIXING



EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)









EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 99%)

PROGRESS: All works completed. Common load charging completed.

EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)







EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 99%)

PROGRESS:

CIVIL FOUNDATIONS - 100% completed **EQUIPMENT ERECTION** - 100% completed - FP & TP erected STRUCTURE ERECTION **CABLE LAYING** - 100% completed **CABLE END TERMINATION** - 99% completed - 100% Completed **LT PANEL** - 100% Completed) LIGHTNING ARRESTOR - 99% Completed STREET LIGHT - 99% Completed **TELEPHONE SYSTEM** -IR TEST completed **TESTING**