PROGRESS BHUBANESWAR AS ON 15 JUN 2018 WEB UP DATE FOR AFNHB BHUBANESWAR PROJECT

1. Dismantling and removing of Batching plant 100% completed,

2. External Development Work

- (a) Roads works completed
- (b) Drains work completed.
- (c) Cable laying completed.

(d) Fixing of street lights except 2 nos completed these 2 nos poles are to be installed at temporary substation of M/s OICL. The same shall be completed after energization of substation.

3. <u>Lift Work</u>: Commissioning of Lifts, 06 blocks completed, balance one block work in progress EDC by end Jun 18.

4. **Swimming Pool:** Civil work completed, finishing work is in progress EDC 30 Jun 18

5. **<u>STP</u>**: Civil work and mechanical installation completed. Testing in progress.

6. **<u>Towers</u>**: Balance work of firefighting, internal wirings, paintings, door fixing in few flats are in progress. No major work pending. Testing and commissioning of all services is in progress.

7. <u>Energization of Sub Station</u>: Medium Voltage (MV) Inspection by CESU authority undertaken on 19 May 18 for substations and other electro mechanical items. Energization of substation is expected by end June 18.

8. <u>Status of Completion/Occupancy Certificate</u>: NOCs from CESU, BMC obtained inspection by PH & MOE & F completed, waiting for reports, inspection by fire Dept EDC 30 JUNE. On receipt of all NOCs, application for OC will be made to BDA.

9. **Possession:** Handing over of DUs commenced from 18 May 18. 6 Nos Dus have been handing over.(5-Officer Block,1-Sailor Block)

10. Handing over of DUs of top floor of Block A and G will commence from 11 Jun 18. Similarly handing over of Block B and E DUs would commence w.e.f. 25 Jun 18.

11. Average daily labour strength at site during May 18 - June 18 is 161.



TOWER NO: A OFFICERS (Overall completion-99.5%)

Total floors:S1+S2+8Total Flats:32**PROGRESS:**

CHINA WARE FITTING PAINTING (INTERNAL) EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK CP FITTING

- 100% completed
- 100% (Final paint completed)
- 100% completed
- 99% completed
- 100% completed
- 95% completed
- 100% completed



TOWER NO: B OFFICERS (Overall completion-97.85%)

Total floors:S1+S2+8Total Flats:32

PROGRESS:

PLUMBING EXTERNAL PAINT ELECTRICAL WORK FIRE FIGHTING WORK DOOR & WINDOW FIXING CHINA WARE FITTING 95% completed
100% completed
99% completed
95% completed
100% completed
95% completed



TOWER NO: C OFFICERS (Overall completion-96.5%)

Total floors:S1+S2+8Total Flats:32

PROGRESS:

PLUMBING CHINA WARE FITTING EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 90% completed
- 90% completed
- -100% completed
- 99% completed
- 100% completed
- 95% completed



<u>TOWER NO</u>: D OFFICERS (Overall completion-98.5%)

Total floors: S1+S2+8 Total Flats: 32

PROGRESS:

CHINA WARE FITTING EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK CP FITTING

- 100% completed
- -100% completed
- 99% completed
- 100% completed
- 95% completed
- -100% completed



TOWER NO: E SAILOR (Overall completion-96.25%)

Total floors:S1+S2+11Total Flats:43

PROGRESS:

EXTERNAL PAINT PLUMBING ELECTRICAL WORK FIRE FIGHTING WORK DOOR & WINDOW FIXING CHINA WARE FITTING

- 100% completed
- 80% completed
- 98% completed
- 95% completed
- 100% completed
- -100% completed



TOWER NO: F SAILOR (Overall completion-93.55%)

Total floors:S1+S2+11Total Flats:43

PROGRESS:

TILING PLUMBING EXTERNAL PAINT ELECTRICAL WORK FIRE FIGHTING WORK DOOR & WINDOW FIXING STAIRCASE RAILING FALSE CEILING

- 100% completed
 80% completed
 90% completed
 98% completed
 95% completed
 100% completed
 100% completed
- -100% Completed



TOWER NO: G SAILOR (Overall completion-99.5%)

Total floors:S1+S2+11Total Flats:42

PROGRESS:

EXTERNAL PAINT CHINA WIRE FITTING ELECTRICAL WORK FIRE FIGHTING WORK CP FITTING

- 100% completed
- 100% completed
- 98% completed
- 95% completed
- 100% completed



TOWER NO: COMMUNITY CENTER (Overall completion-95.10%)

Total floors: G+1

PROGRESS:

BRICK WORK PAINTING ELECTRICAL WORK FIRE FIGHTING WORK DOOR & WINDOW FIXING EXTERNAL PAINT TILING

- 90% completed
- 100% (1st coat paint completed)
- 90% completed
- 85% completed
- 60% completed
- 75% completed
- 80% completed

SWIMMING POOL



<u>SWIMMING POOL-</u> (Overall completion- 77%)

PROGRESS: Plastering work in progress.

LIFT WORK



LIFT WORK (Overall completion- 95%)

Lift commissioning completed A, B, C, D, E & G block.

Commissioning of lift in F block will be completed by 30 JUNE 18.

EXTERNAL DRAIN WORK



EXTERNAL DRAIN WORK (Overall completion- 99%)

PROGRESS: Cover casting work in progress.

RECHARGE PIT



<u>RECHARGE PIT</u> (Overall completion- 96%)

PROGRESS: Back filling work in progress.

<u>GATE</u>



PROGRESS: Fixing work in progress.

PUMP ROOM



PUMP ROOM

PROGRESS: Installation completed & testing work in progress.

EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)



EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 90%)

PROGRESS: All works completed

N.B:- CESU DIRECTED TO MRT DIVISION FOR INSTALLATION OF COMMON METERING & CHARGING WILL BE DONE SHORTLY.

EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)



CABLE LAYING FROM TRF TO PANEL AT S/S-2







EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 96%)

PROGRESS:

CIVIL FOUNDATIONS EQUIPMENT ERECTION STRUCTURE ERECTION CABLE LAYING CABLE END TERMINATION LT PANEL LIGHTNING ARRESTOR STREET LIGHT TELEPHONE SYSTEM TESTING - 95% completed

- 100% completed
- FP & TP erected
- 100% completed
- 95% completed
- 100% Completed
- 100% Completed)
- 75% Completed
- Telephone cabling work in progress
- -IR TEST completed