AVERAGE DAILY LABOUR IN NOV-DEC: 220



TOWER NO: A1 OFFICERS (Overall completion-93%)

Total floors: S1+S2+8 Total Flats: 32

PROGRESS:

STRUCTURAL WORK - 100% completed (Terrace structure completed)

BRICK WORK - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 100% completed
PLUMBING - 100% completed
CHINA WARE FITTING - 95% completed

PAINTING (INTERNAL) - 90% (1st coat paint completed)

EXTERNAL PAINT
- 80% completed
- 90% completed
- 90% completed
- 90% completed
- 90% completed
- 40% completed
- 40% completed

CP FITTING - 85% completed
BALCONY RAILING - 100% completed
STAIRCASE RAILING - 100% completed
FALSE CEILING -100% Completed



TOWER NO: A2 OFFICERS (Overall completion-89.50%)

Total floors: S1+S2+8
Total Flats: 32

PROGRESS: STRUCTURAL WORK - 100% completed (Terrace structure)

BRICK WORK - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 100% completed
- 100% completed
- 80% completed

PAINTING -75% (1st coat paint completed)

EXTERNAL PAINT
-75% completed

ELECTRICAL WORK
-75% completed
-35% completed
-35% completed
-60% completed
-100% completed
-100% completed
-90% completed
-70% completed
-70% completed



TOWER NO: A3 OFFICERS (Overall completion-90.44%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS:

STRUCTURAL WORK - 100% completed (terrace structure completed)

BRICK WORK - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 95% completed
INTERNAL PLASTERING - 100% completed
TILING - 100% completed
PLUMBING - 80% completed
CHINA WARE FITTING - 90% completed

PAINTING -80% (1st coat paint completed)

EXTERNAL PAINT
-80% completed
-80% completed
-80% completed
-60% completed
-30% completed
-30% completed
-100% completed
-100% completed
-90% completed



TOWER NO: A4 OFFICERS (Overall completion-91%)

Total floors: S1+S2+8 **Total Flats:** 32

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING/GRANITE

PLUMBING

CHINA WARE FITTING

PAINTING

EXTERNAL PAINT

ELECTRICAL WORK DOOR & WINDOW FIXING

FIRE FIGHTING WORK

CP FITTING

FALSE CEILING

BALCONY RAILING STAIRCASE RAILING - 100% completed (Terrace structure completed)

- 100% completed (Except lower & upper stilt)

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 90% completed

- 80% (1st coat paint completed)

-80% completed

- 78% completed

- 60% completed

- 35% completed -60% completed

-100% completed -100% completed

-50% Completed



TOWER NO: B1 SAILOR (Overall completion-83.24%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

EXTERNAL PAINT PLUMBING

PAINTING

ELECTRICAL WORK

FIRE FIGHTING WORK DOOR & WINDOW FIXING CHINA WARE FITTING - 100% completed

- 100% completed

- 100% completed

100% completed100% completed

- 80% completed

- 80% completed

- 80% (1st coat paint completed)

- 60% completed- 20% completed

- 50% completed

- 90% completed



TOWER NO: B2 SAILOR (Overall completion-73.30%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 100% completed
EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 80% completed
PLUMBING - 70% completed

PAINTING - (2nd coat putty 90% completed)

EXTERNAL PAINT -80% completed
ELECTRICAL WORK - 50% completed
FIRE FIGHTING WORK - 15% completed
DOOR & WINDOW FIXING - 30% completed



TOWER NO: B3 SAILOR (Overall completion-94.67%)

Total floors: S1+S2+11
Total Flats: 42

PROGRESS:

STRUCTURAL WORK - 100% completed (Terrace structure completed)

BRICK WORK - 100% completed
EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed

TILING - 100% completed
- 100% completed
- 100% completed
- 100% completed

PAINTING - 80% (1st coat paint completed)

EXTERNAL PAINT

CHINA WIRE FITTING

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

CP FITTING

-80% completed
-87% completed
-100% completed
-25% completed
-85% completed

CP FITTING -85% completed
BALCONY RAILING -100% completed
FALSE CEILING -100% Completed
STAIRCASE RAILING -100% completed



TOWER NO: COMMUNITY CENTER (Overall completion-87%)

Total floors: G+1

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 90% completed **EXTERNAL PLASTERING** - 90% completed

INTERNAL PLASTERING - 90% completed

PAINTING - (only 1st coat putty completed)

ELECTRICAL WORK - 30% completed FIRE FIGHTING WORK - 10% completed


EXTERNAL SERVICES



UNDER GROUND RESERVOIR- (Overall completion-53.68%)

PROGRESS: Manhole cover fixing completed.

BOUNDARY WALL



BOUNDARY WALL- (Overall completion- 77.25%)

PROGRESS: Plastering work in progress

SWIMMING POOL



SWIMMING POOL- (Overall completion- 47%)

PROGRESS: Wall casting completed.

SWERAGE TRETMENT PLANT



SWERAGE TRETMENT PLANT (Overall completion- 63%)

PROGRESS: Tiling work & plastering work completed.

LIFT WORK



LIFT WORK (Overall completion- 50%)

PROGRESS: 14 Nos lift material has arrived at site. And 10 nos lift work in progress all block

Lift commissioning completed A1 & A4 block.

EXTERNAL DRAIN WORK



EXTERNAL DRAIN WORK (Overall completion- 20%)

PROGRESS: Slab casting work in progress.

FIREFIGHTING WORK



FIREFIGHTING WORK

PROGRESS: LSF sprinkler work.

EXTERNAL ROAD & RETAINING WALL WORK



EXTERNAL ROAD & RETAINING WALL WORK (Overall completion- 41.29%)

PROGRESS: PCC & VDF flooring work in progress.

EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)









EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 89%)

PROGRESS: SP ERECTION - 100% completed

DP ERECTION - 100% completed
FP ERECTION - 100% completed
CONDUCTOR STRINGING - 100% completed
CIVIL FOUNDATIONS -100% completed

EQUIPMENT ERECTION - Transformer, VCB, Isolator, CT & PT and CR panel erected

STRUCTURE ERECTION - CT, PT, and Isolator & VCB structure erected

CABLE LAYING - 100% completed **CABLE END TERMINATION** - 100% completed

EARTHING - 100% completed
CONTROL CABLE - 80% completed
AB CABLE -50% completed

EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)









EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 61%)

PROGRESS:

CIVIL FOUNDATIONS EQUIPMENT ERECTION

STRUCTURE ERECTION

CABLE LAYING

CABLE END TERMINATION

EARTHING OH LINE

DG FUEL ROOM

LT PANEL

LIGHTNING ARRESTOR

STREET LIGHT

TELEPHONE SYSTEM

TESTING

- 95% completed

- Transformers, DG sets erection

- FP & TP erected

- Started at officer block

- To be done

- Completed

-Completed

- Completed

- 05 nos transformer panel erected

- Earthing of officers block completed

- Pole foundation work started

- To be done (Layout started)

-IR TEST completed