

TOWER NO: A1 OFFICERS (Overall completion-83.05%)

Total floors: S1+S2+8 Total Flats: 32

PROGRESS:

STRUCTURAL WORK - 100% completed (Except terrace structure) - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 95% completed
INTERNAL PLASTERING - 100% completed
TILING - 100% completed
PLUMBING - 100% completed

CHINA WIRE FITTING - 15% completed
PAINTING - (2nd coat putty completed)

ELECTRICAL WORK - 50% completed **DOOR & WINDOW FIXING** - 60% completed **FIRE FIGHTING WORK** - 5% completed



TOWER NO: A2 OFFICERS (Overall completion-66.85%)

Total floors: S1+S2+8
Total Flats: 32

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING PLUMBING

PAINTING

ELECTRICAL WORK FIRE FIGHTING WORK

- 100% completed (Except terrace structure)

- 100% completed (Except lower & upper stilt)

60% completed100% completed

- To be done

- 15% completed

- (only 1st coat putty completed)

- 35% completed- 5% completed



TOWER NO: A3 OFFICERS (Overall completion-63.69%)

PLUMBING

Total floors: S1+S2+8
Total Flats: 32

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 100% completed (Except lower & upper stilt)

- 15% completed

EXTERNAL PLASTERING - 60% completed - 100% completed - TILING - To be done

PAINTING - (only 1st coat putty completed)

ELECTRICAL WORK - 35% completed **FIRE FIGHTING WORK** - 5% completed



TOWER NO: A4 OFFICERS (Overall completion-71.16%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING - 95% completed
INTERNAL PLASTERING - 100% completed
TILING/GRANITE - 70% completed
PLUMBING - 100% completed

PAINTING - (only 1st coat putty completed)

- 100% completed (Except terrace structure)

- 100% completed (Except lower & upper stilt)

ELECTRICAL WORK - 35% completed FIRE FIGHTING WORK - 5% completed



TOWER NO: B1 SAILOR (Overall completion-62.28%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK

RUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 90% completed

EXTERNAL PLASTERING - To be done

INTERNAL PLASTERING - 80% completed TILING - To be done

PLUMBING - 20% completed

PAINTING - (only 1st coat putty up to 8th floor completed)

ELECTRICAL WORK - 30% completed **FIRE FIGHTING WORK** - 5% completed



TOWER NO: B2 SAILOR (Overall completion-55.58%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK - 92% completed (up to 10th floor completed)

BRICK WORK - 73% completed

EXTERNAL PLASTERING - To be done
INTERNAL PLASTERING - 55% completed
TILING - To be done

PLUMBING - To be done

PAINTING - (only 1st coat putty 4th floor completed)

ELECTRICAL WORK - 25% completed



TOWER NO: B3 SAILOR (Overall completion-88.47%)

Total floors: S1+S2+11

Total Flats: 42

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 100% completed
EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 95% completed
PLUMBING - 100% completed

PAINTING - 90% 2nd coat putty complete

CHINA WIRE FITTING - 80% completed
ELECTRICAL WORK - 60% completed
DOOR & WINDOW FIXING - 90% completed
FIRE FIGHTING WORK - 15% completed



TOWER NO: COMMUNITY CENTER (Overall completion-87%)

Total floors: G+1

PROGRESS: STRUCTURAL WORK

BRICK WORK

- 90% completed - 90% completed **EXTERNAL PLASTERING INTERNAL PLASTERING** - 90% completed

- To be done TILING - To be done **PLUMBING**

- (only 1st coat putty completed) **PAINTING**

- 100% completed (Except terrace structure)

- 30% completed **ELECTRICAL WORK**

EXTERNAL SERVICES



Under Ground Reservoir- (Overall completion-15%)

PROGRESS: Wall reinforcement & shuttering work in progress. Progress will be indicated only after casting

RETAINING WALL



RETAINING WALL- (Overall completion- 65%)

PROGRESS: Wall casting work in progress

BOUNDARY WALL



BOUNDARY WALL- (Overall completion- 48.26%)

PROGRESS: Brick work in progress

SWIMMING POOL



SWIMMING POOL

PROGRESS: Excavation work in progress

EXTERNAL ELECTRICAL



EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 42%)

PROGRESS:

SP ERECTION

- 100% completed

DP ERECTION

- 100% completed

FP ERECTION

- 100% completed

CONDUCTOR STRINGING

- 100% completed

CIVIL FOUNDATIONS EQUIPMENT ERECTION

-100% completed

CABLE LAYING

- Only transformer erected

 To be done (Due to non availability of CESU shut down & non procurement of material such as CT, PT & ISOLATOR work has not completed)