AVERAGE DAILY LABOUR IN DEC 2017- JAN 2018: 188



TOWER NO: A1 OFFICERS (Overall completion-95.45%)

Total floors: S1+S2+8 Total Flats: 32

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING
TILING

CHINA WARE FITTING PAINTING (INTERNAL)

PLUMBING

PAINTING (INTERNAL)
EXTERNAL PAINT

ELECTRICAL WORK
DOOR & WINDOW FIXING

FIRE FIGHTING WORK CP FITTING

BALCONY RAILING
STAIRCASE RAILING
FALSE CEILING

- 100% completed (Terrace structure completed)

- 100% completed (Except lower & upper stilt)

100% completed100% completed

- 100% completed- 100% completed- 95% completed

- 100% (1st coat paint completed)

- 80% completed - 92% completed

90% completed50% completed

85% completed100% completed100% completed

-100% Completed



TOWER NO: A2 OFFICERS (Overall completion-90.28%)

Total floors: S1+S2+8 **Total Flats:** 32

PROGRESS: STRUCTURAL WORK

- 100% completed (Terrace structure)

- 100% completed (Except lower & upper stilt) **BRICK WORK**

EXTERNAL PLASTERING - 100% completed **INTERNAL PLASTERING** - 100% completed **TILING** - 100% completed - 80% completed **PLUMBING**

PAINTING -80% (1st coat paint completed)

EXTERNAL PAINT -80% completed **ELECTRICAL WORK** - 80% completed FIRE FIGHTING WORK - 40% completed **DOOR & WINDOW FIXING** - 60% completed **BALCONY RAILING** -100% completed **CHINA WARE FITTING** - 90% completed **STAIRCASE RAILING** - 80% completed



TOWER NO: A3 OFFICERS (Overall completion-92.19%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS: STRUCTURAL WORK - 100% completed (terrace structure completed)

BRICK WORK - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 100% completed
PLUMBING - 90% completed

CHINA WARE FITTING - 90% completed

PAINTING -90% (1st coat paint completed)

EXTERNAL PAINT
-80% completed
-85% completed
-85% completed
-60% completed
-60% completed
-35% completed
-100% completed
-90% completed
-90% completed
-90% completed
-20% Completed



TOWER NO: A4 OFFICERS (Overall completion-93.70%)

Total floors: S1+S2+8 **Total Flats:** 32

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING/GRANITE **PLUMBING**

CHINA WARE FITTING

PAINTING

EXTERNAL PAINT

ELECTRICAL WORK DOOR & WINDOW FIXING

FIRE FIGHTING WORK

CP FITTING

BALCONY RAILING STAIRCASE RAILING FALSE CEILING

- 100% completed (Terrace structure completed)

- 100% completed (Except lower & upper stilt)

- 100% completed

- 100% completed

- 100% completed - 100% completed

- 90% completed

-100% (1st coat paint completed)

-80% completed

- 80% completed

- 60% completed

- 50% completed -60% completed

-100% completed -100% completed

-70% Completed



- 100% completed

- 100% completed - 100% completed

- 100% completed - 100% completed

TOWER NO: B1 SAILOR (Overall completion-86.49%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

EXTERNAL PAINT - 90% completed **PLUMBING** - 80% completed - 90% (1st coat paint completed)

PAINTING

ELECTRICAL WORK - 70% completed FIRE FIGHTING WORK - 30% completed **DOOR & WINDOW FIXING** - 50% completed - 90% completed **CHINA WARE FITTING**

FALSE CEILING -80% Completed



TOWER NO: B2 SAILOR (Overall completion-80.65%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 100% completed
EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 95% completed
PLUMBING -80% completed

PAINTING - (1st coat paint 80% completed)

EXTERNAL PAINT

ELECTRICAL WORK


FIRE FIGHTING WORK

DOOR & WINDOW FIXING

-80% completed

- 20% completed

- 35% completed



TOWER NO: B3 SAILOR (Overall completion-96.22%)

Total floors: S1+S2+11

Total Flats: 42

PROGRESS:

STRUCTURAL WORK - 100% completed (Terrace structure completed)

BRICK WORK - 100% completed

EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed

TILING - 100% completed PLUMBING - 100% completed

PAINTING - 100% (1st coat paint completed)

EXTERNAL PAINT -80% completed
CHINA WIRE FITTING - 80% completed
ELECTRICAL WORK - 87% completed
DOOR & WINDOW FIXING - 100% completed

FIRE FIGHTING WORK - 40% completed
- 40% completed
- 85% completed

FALSE CEILING - 100% completed -100% Completed -100% completed -100% completed



TOWER NO: COMMUNITY CENTER (Overall completion-87%)

Total floors: G+1

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 90% completed
EXTERNAL PLASTERING - 90% completed

O0% completed

INTERNAL PLASTERING - 90% completed

PAINTING - (only 1st coat putty completed)

ELECTRICAL WORK - 30% completed FIRE FIGHTING WORK - 10% completed

EXTERNAL SERVICES



UNDER GROUND RESERVOIR- (Overall completion-53.68%)

PROGRESS: Manhole cover fixing completed.

BOUNDARY WALL



BOUNDARY WALL- (Overall completion- 85.25%)

PROGRESS: Painting work in progress

SWIMMING POOL



SWIMMING POOL- (Overall completion- 53%)

PROGRESS: Balancing tank tiling work in progress & Accessories reached at site.

SWERAGE TRETMENT PLANT





SWERAGE TRETMENT PLANT (Overall completion- 77%)

PROGRESS: Installation completed.

LIFT WORK



LIFT WORK (Overall completion- 65%)

PROGRESS: 14 Nos lift material has arrived at site. And 10 nos lift work in progress all block

Lift commissioning completed A1 & A4 block.

EXTERNAL DRAIN WORK



EXTERNAL DRAIN WORK (Overall completion- 45%)

PROGRESS: Raft casting work in progress.

FIREFIGHTING WORK



FIREFIGHTING WORK

PROGRESS: Ring line work near sailor block.

EXTERNAL ROAD & RETAINING WALL WORK



EXTERNAL ROAD & RETAINING WALL WORK (Overall completion- 43.28%)

PROGRESS: PCC work in progress.


RECHARGE PIT



RECHARGE PIT (Overall completion- 20%)

PROGRESS: Wall casting work in progress.

CEMENT JALI



PROGRESS: A1 block completed & A4 block work in progress.

EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)









EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 89%)

PROGRESS: SP ERECTION - 100% completed

DP ERECTION - 100% completed **FP ERECTION** - 100% completed **CONDUCTOR STRINGING** - 100% completed

CIVIL FOUNDATIONS -100% completed **EQUIPMENT ERECTION** -Transformer, VCB, Isolator, CT & PT and CR panel erected

STRUCTURE ERECTION - CT, PT, and Isolator & VCB structure erected

CABLE LAYING - 100% completed

CABLE END TERMINATION - 100% completed
EARTHING - 100% completed
- 100% completed

CONTROL CABLE - 80% completed **AB CABLE** -50% completed

EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)









EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 65%)

PROGRESS:

CIVIL FOUNDATIONS EQUIPMENT ERECTION

STRUCTURE ERECTION

CABLE LAYING

CABLE END TERMINATION

EARTHING

OH LINE

DG FUEL ROOM

LT PANEL

LIGHTNING ARRESTOR

STREET LIGHT

TELEPHONE SYSTEM

TESTING

- 95% completed

- Transformers, DG sets erection

- FP & TP erected

- Started at officer block

- To be done

- Completed

-Completed

- Completed

- 05 nos transformer panel erected

- Earthing of officers block completed (A3 & A4 BLOCK)

- Pole foundation work started

- HDPE pipe laying work in progress

-IR TEST completed