AVERAGE DAILY LABOUR IN JUN - JUL: 292



TOWER NO: A1 OFFICERS (Overall completion - 92.16%)

Total floors: S1+S2+8 **Total Flats:** 32

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING PLUMBING

CHINA WARE FITTING

PAINTING

CP FITTING

EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING

FIRE FIGHTING WORK

BALCONY RAILING STAIRCASE RAILING FALSE CEILING

- 100% completed (terrace structure completed)

- 100% completed (Except lower & upper stilt)

- 95% completed - 100% completed

- 100% completed

- 100% completed

- 95% completed

- 75% (1st coat paint completed)

-80% completed

- 70% completed

- 90% completed

- 35% completed

-85% completed

-100% completed

-40% completed

-100% Completed



TOWER NO: A2 OFFICERS (Overall completion-82.56%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING
PLUMBING
PAINTING

EXTERNAL PAINT

ELECTRICAL WORK
FIRE FIGHTING WORK
DOOR & WINDOW FIXING
BALCONY RAILING

- 100% completed (Except terrace structure)

- 100% completed (Except lower & upper stilt)

90% completed100% completed80% completed

- 70% completed

- (2nd coat putty completed)

-25% completed - 55% completed - 15% completed - 40% completed -100% completed



TOWER NO: A3 OFFICERS (Overall completion-86.99%)

Total floors: S1+S2+8
Total Flats: 32

PROGRESS: STRUCTURAL WORK - 100% completed (terrace structure completed)

BRICK WORK

EXTERNAL PLASTERING - 95% completed
INTERNAL PLASTERING - 100% completed
TILING - 100% completed
PLUMBING - 65% completed

CHINA WARE FITTING - 90% completed

PAINTING - (2nd coat putty completed)

- 100% completed (Except lower & upper stilt)

EXTERNAL PAINT
-70% completed
ELECTRICAL WORK
- 65% completed
DOOR & WINDOW FIXING
FIRE FIGHTING WORK
- 15% completed
BALCONY RAILING
-100% completed



TOWER NO: A4 OFFICERS (Overall completion-87.80%)

Total floors: S1+S2+8 **Total Flats:** 32

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING TILING/GRANITE

PLUMBING

CHINA WARE FITTING

PAINTING

EXTERNAL PAINT

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

CP FITTING

BALCONY RAILING

- 100% completed (Terrace structure completed)

- 100% completed (Except lower & upper stilt)

- 95% completed

- 100% completed

- 100% completed

- 100% completed

- 90% completed

- 75% (1st coat paint completed)

-80% completed

- 65% completed

- 60% completed

- 30% completed

-60% completed

-100% completed



TOWER NO: B1 SAILOR (Overall completion-68.88%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS:

STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 95% completed

EXTERNAL PLASTERING - 95% completed
INTERNAL PLASTERING - 100% completed
TILING - 20% completed
PLUMBING - 65% completed

PAINTING - (only 1st coat putty completed)

ELECTRICAL WORK - 40% completed **FIRE FIGHTING WORK** - 15% completed



TOWER NO: B2 SAILOR (Overall completion-60.26%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS:

STRUCTURAL WORK

BRICK WORK

- 95% completed **EXTERNAL PLASTERING** - 60% completed **INTERNAL PLASTERING** - 95% completed

TILING - To be done - 40% completed **PLUMBING**

- (only 1st coat putty 11th floor completed) **PAINTING**

- 100% completed (Except terrace structure)

- 40% completed **ELECTRICAL WORK** FIRE FIGHTING WORK - 15% completed

PROGRESS BHUBANESWAR AS ON 15 JUL 2017



TOWER NO: B3 SAILOR (Overall completion-90.67%)

Total floors: S1+S2+11

Total Flats: 42

PROGRESS: STRUCTURAL WORK - 100% completed (Terrace structure completed)

BRICK WORK - 100% completed
EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 95% completed
PLUMBING - 100% completed

PAINTING - 75% (1st coat paint completed)

EXTERNAL PAINT -60% completed **CHINA WIRE FITTING** - 80% completed - 75% completed **ELECTRICAL WORK DOOR & WINDOW FIXING** - 90% completed FIRE FIGHTING WORK - 20% completed **CP FITTING** -85% completed **BALCONY RAILING** - 90% completed **FALSE CEILING** -100% Completed

PROGRESS BHUBANESWAR AS ON 15 JUL 2017



TOWER NO: COMMUNITY CENTER (Overall completion-87%)

Total floors: G+1

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

PAINTING

ELECTRICAL WORK
FIRE FIGHTING WORK

- 100% completed (Except terrace structure)

90% completed90% completed

- 90% completed

- (only 1st coat putty completed)

- 30% completed - 10% completed



CONNECTING SLAB (B2 & B3 BLOCK)

PROGRESS: connecting slab in-between B2 & B3 casted.

EXTERNAL SERVICES



UNDER GROUND RESERVOIR- (Overall completion-30.25%)

PROGRESS: Pump room slab casted.

BOUNDARY WALL



BOUNDARY WALL- (Overall completion- 60.5%)

PROGRESS: Copping casting & clamp fixing work in progress


SWIMMING POOL



SWIMMING POOL- (Overall completion- 25%)

PROGRESS: Wall reinforcement & shuttering work in progress.

SWERAGE TRETMENT PLANT



SWERAGE TRETMENT PLANT (Overall completion- 23.3%)

PROGRESS: Wall shuttering work in progress.


LIFT WORK



LIFT WORK(Overall completion- 28%)

PROGRESS: 04Nos lift material has arrived at site. And 02nos lift work started at A1 & A4 block (Channel fixing complete).

EXTERNAL DRAIN WORK



EXTERNAL DRAIN WORK

PROGRESS: Reinforcement & shuttering work in progress.

EXTERNAL ELECTRICAL AT CESU PREMISES (A)







EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 85%)

PROGRESS: SP ERECTION - 100% completed

DP ERECTION - 100% completed
FP ERECTION - 100% completed
CONDUCTOR STRINGING - 100% completed
CIVIL FOUNDATIONS -100% completed

EQUIPMENT ERECTION - Transformer, VCB, Isolator, CT & PT and CR panel erected

STRUCTURE ERECTION - CT, PT, and Isolator & VCB structure erected

CABLE LAYING - 95%
CABLE END TERMINATION - 85%
EARTHING - 100%

PROGRESS BHUBANESWAR AS ON 15 JUL 2017 EXTERNAL ELECTRICAL AT AFNHB SITE PREMISES (B)



EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 56%)

PROGRESS:

CIVIL FOUNDATIONS - 95% completed

EQUIPMENT ERECTION - Transformers, DG sets erection

STRUCTURE ERECTION - FP & TP erected

CABLE LAYING - To be done

CABLE END TERMINATION - To be done

EARTHING - Completed

OH LINE -Completed

FENCING WALL - Completed

DG FUEL ROOM - Completed

LT PANEL -PO placed