AVERAGE DAILY LABOUR IN MAY- JUN: 348



TOWER NO: A1 OFFICERS (Overall completion-92.07%)

Total floors: S1+S2+8 **Total Flats:** 32

PROGRESS:

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

PLUMBING

CHINA WARE FITTING

PAINTING

EXTERNAL PAINT

ELECTRICAL WORK DOOR & WINDOW FIXING

FIRE FIGHTING WORK

CP FITTING

BALCONY RAILING

- 100% completed (terrace structure completed)

- 100% completed (Except lower & upper stilt)

- 95% completed

- 100% completed - 100% completed

- 100% completed

- 95% completed

- 75% (1st coat paint completed)

-80% completed


- 70% completed

- 90% completed

- 35% completed

-85% completed

- 70% completed



TOWER NO: A2 OFFICERS (Overall completion-80.46%)

Total floors: S1+S2+8
Total Flats: 32

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING - 90% completed
INTERNAL PLASTERING - 100% completed
TILING - 65% completed
PLUMBING - 70% completed

PAINTING - (only 1st coat putty completed)

- 100% completed (Except terrace structure)

- 100% completed (Except lower & upper stilt)

EXTERNAL PAINT -25% complete

ELECTRICAL WORK - 45% completed

FIRE FIGHTING WORK - 15% completed



TOWER NO: A3 OFFICERS (Overall completion-83.99%)

Total floors: S1+S2+8
Total Flats: 32

PROGRESS: STRUCTURAL WORK - 100% completed (terrace structure completed)

BRICK WORK - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 95% completed
INTERNAL PLASTERING - 100% completed
TILING - 85% completed
PLUMBING - 65% completed
CHINA WARE FITTING - 90% completed

PAINTING - (only 2nd coat putty completed)

EXTERNAL PAINT

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

-20% completed

-30% completed

-15% completed



TOWER NO: A4 OFFICERS (Overall completion-84.04%)

Total floors: S1+S2+8

Total Flats: 32 **PROGRESS:**

STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING TILING/GRANITE **PLUMBING**

CHINA WARE FITTING

- 60% (1st coat paint completed) **PAINTING**

- 95% completed - 100% completed

- 100% completed - 100% completed

- 90% completed

- 100% completed (Terrace structure completed)

- 100% completed (Except lower & upper stilt)

-80% completed **EXTERNAL PAINT ELECTRICAL WORK** - 65% completed **DOOR & WINDOW FIXING** - 40% completed FIRE FIGHTING WORK - 30% completed -20% completed **CP FITTING**



TOWER NO: B1 SAILOR (Overall completion-65.06%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 95% completed

EXTERNAL PLASTERING - 90% completed
INTERNAL PLASTERING - 95% completed
TILING -05% completed
PLUMBING - 65% completed

PAINTING - (only 1st coat putty up to 10th floor completed)

ELECTRICAL WORK - 40% completed **FIRE FIGHTING WORK** - 15% completed



TOWER NO: B2 SAILOR (Overall completion-59.46%)

Total floors: \$1+\$2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 95% completed

EXTERNAL PLASTERING - 10% completed
INTERNAL PLASTERING - 95% completed
TILING - To be done
PLUMBING - 40% completed

PAINTING - (only 1st coat putty 11th floor completed)

ELECTRICAL WORK - 40% completed FIRE FIGHTING WORK - 15% completed



TOWER NO: B3 SAILOR (Overall completion-90.42%)

Total floors: S1+S2+11

Total Flats: 42

PROGRESS: STRUCTURAL WORK - 100% completed (Terrace structure completed)

BRICK WORK - 100% completed
EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 95% completed
PLUMBING - 100% completed

PAINTING - 40% (1st coat paint completed)

EXTERNAL PAINT

CHINA WIRE FITTING

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

CP FITTING

BALCONY RAILING

-40% completed
-75% completed
-90% completed
-85% completed
-90% completed

FALSE CEILING -80% Completed



TOWER NO: COMMUNITY CENTER (Overall completion-87%)

Total floors: G+1


PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 90% completed

EXTERNAL PLASTERING - 90% completed **INTERNAL PLASTERING** - 90% completed

PAINTING - (only 1st coat putty completed)

ELECTRICAL WORK - 30% completed FIRE FIGHTING WORK - 10% completed



CONNECTING SLAB (B2 & B3 BLOCK)

PROGRESS: Slab shuttering work in progress.

EXTERNAL SERVICES



UNDER GROUND RESERVOIR- (Overall completion-30.25%)

PROGRESS: Pump room slab casted.

BOUNDARY WALL



BOUNDARY WALL- (Overall completion- 53.5%)

PROGRESS: Copping casting & clamp fixing work in progress

SWIMMING POOL



SWIMMING POOL- (Overall completion- 18%)

PROGRESS: Raft casted & wall reinforcement work in progress.

SWERAGE TRETMENT PLANT



SWERAGE TRETMENT PLANT (Overall completion- 23%)

PROGRESS: Raft casted & wall reinforcement work in progress.

LIFT WORK



LIFT WORK(Overall completion- 26%)

PROGRESS: 04Nos lift material has arrived at site. And 02nos lift work started at A1 block (Channel fixing).

EXTERNAL DRAIN WORK



EXTERNAL DRAIN WORK

PROGRESS: PCC work in progress.

EXTERNAL ELECTRICAL AT CESU PREMISES (A)





EXTERNAL ELECTRICAL (PART-A) - (Overall completion-80%)

PROGRESS: SP ERECTION - 100% completed

DP ERECTION - 100% completed
FP ERECTION - 100% completed
CONDUCTOR STRINGING - 100% completed
CIVIL FOUNDATIONS -100% completed

EQUIPMENT ERECTION - Transformer, VCB, Isolator, CT & PT erected **STRUCTURE ERECTION** - CT, PT, and Isolator & VCB structure erected

CABLE LAYING - 85%
CABLE END TERMINATION - 85%
EARTHING - 100%

PROGRESS BHUBANESWAR AS ON 15 JUN 2017 EXTERNAL ELECTRICAL AT AFNHB SITE PREMISES (B)









EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 55%)

PROGRESS:

CIVIL FOUNDATIONS - 95% completed

EQUIPMENT ERECTION - Transformers, DG sets erection

STRUCTURE ERECTION - FP & TP erection

CABLE LAYING - To be done

CABLE END TERMINATION - To be done

EARTHING - Completed

OH LINE -Completed FENCING WALL -Continuing

DG FUEL ROOM -Continuing