AVERAGE DAILY LABOUR IN APR-MAY: 365



TOWER NO: A1 OFFICERS (Overall completion-91.61%)

Total floors: S1+S2+8 Total Flats: 32 PROGRESS: S

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WARE FITTING PAINTING EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK CP FITTING BALCONY RAILING

- 100% completed (terrace structure completed)
- 100% completed (Except lower & upper stilt)
- 95% completed
- 100% completed
- 100% completed
- 100% completed
- 95% completed
- 75% (1st coat paint completed)
- -50% completed
- 65% completed
- 90% completed
- 30% complete
- -85% completed
 - 70% completed



TOWER NO: A2 OFFICERS (Overall completion-78.86%)

Total floors:S1+S2+8Total Flats:32

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING PAINTING EXTERNAL PAINT ELECTRICAL WORK FIRE FIGHTING WORK

- 100% completed (Except terrace structure)
- 100% completed (Except lower & upper stilt)
- 90% completed
- 100% completed
- 50% completed
- 70% completed
- (only 1st coat putty completed)
- -25% complete
- 40% completed
- 15% completed



TOWER NO: A3 OFFICERS (Overall completion-83.34%)

Total floors:S1+S2+8Total Flats:32

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WARE FITTING PAINTING EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed (terrace structure completed)
- 100% completed (Except lower & upper stilt)
- 95% completed
- 100% completed
- 85% completed
- 65% completed
- 90% completed
- (only 2nd coat putty completed)
- -5% completed
- 40% completed
- 5% completed
- 15% completed



TOWER NO: A4 OFFICERS (Overall completion-83.43%)

Total floors: S1+S2+8 Total Flats: 32

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING/GRANITE PLUMBING CHINA WARE FITTING PAINTING EXTERNAL PAINT ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK CP FITTING

- 100% completed (Terrace structure completed)
- 100% completed (Except lower & upper stilt)
- 95% completed
- 100% completed
- 100% completed
- 100% completed
- 90% completed
- 60% (1st coat paint completed)
- -50% completed
- 65% completed
- 40% completed
- 30% completed
- -20% completed



TOWER NO: B1 SAILOR (Overall completion-64.46%)

Total floors:S1+S2+11Total Flats:43

PROGRESS: ST

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING PAINTING ELECTRICAL WORK FIRE FIGHTING WORK

- 100% completed (Except terrace structure)
- 95% completed
- 80% completed
- 95% completed
- To be done
- 65% completed
- (only 1st coat putty up to 9th floor completed)
- 40% completed
- 15% completed



TOWER NO: B2 SAILOR (Overall completion-59.11%)

Total floors:S1+S2+11Total Flats:43

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING PAINTING ELECTRICAL WORK FIRE FIGHTING WORK

- 100% completed (Except terrace structure)
- 95% completed
- 5% completed
- 90% completed
- To be done
- 40% completed
- (only 1st coat putty 7th floor completed)
- 40% completed
- 10% completed



TOWER NO: B3 SAILOR (Overall completion-89.80%)

Total floors:S1+S2+11Total Flats:42

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING PAINTING EXTERNAL PAINT CHINA WIRE FITTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK CP FITTING BALCONY RAILING

- 100% completed (Terrace structure completed)
- 100% completed
- 100% completed
- 100% completed
- 95% completed
- 100% completed
- 40% (1st coat paint completed)
- -40% completed
- 80% completed
- 75% completed
- 90% completed
- 20% completed
- -85% completed
 - 10% completed



TOWER NO: COMMUNITY CENTER (Overall completion-87%)

Total floors: G+1

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING PAINTING ELECTRICAL WORK FIRE FIGHTING WORK

- 100% completed (Except terrace structure)
- 90% completed
- 90% completed
- 90% completed
- (only 1st coat putty completed)
- 30% completed
- 10% completed



CONNECTING SLAB (B2 & B3 BLOCK)

PROGRESS: Plinth beam casted & column shuttering.

EXTERNAL SERVICES



UNDER GROUND RESERVOIR- (Overall completion-27.44%)

PROGRESS: Slab casted UGR-1 & 2

BOUNDARY WALL



BOUNDARY WALL- (Overall completion- 53.5%)

PROGRESS: Copping casting & clamp fixing work in progress

SWIMMING POOL



SWIMMING POOL- (Overall completion- 5%)

PROGRESS: PCC work in progress

SWERAGE TRETMENT PLANT



SWERAGE TRETMENT PLANT (Overall completion- 4.5%)

PROGRESS: PCC work in progress

FIRE FIGHTING WORK



FIRE FIGHTING WORK

PROGRESS: Sprinkler line in A1 & A4 block Upper stilt floor

PROGRESS BHUBANESWAR AS ON 15 MAY 2017 EXTERNAL ELECTRICAL AT CESU PREMISES(A)



EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 75%)

PROGRESS:

SP ERECTION DP ERECTION FP ERECTION CONDUCTOR STRINGING CIVIL FOUNDATIONS EQUIPMENT ERECTION STRUCTURE ERECTION CABLE LAYING CABLE END TERMINATION EARTHING

- 100% completed
- 100% completed
- 100% completed
- 100% completed
- -100% completed
- Transformer, VCB, Isolator, CT & PT erected
- CT, PT, and Isolator & VCB structure erected

- 85%

- 85%
- 100%

PROGRESS BHUBANESWAR AS ON 15 MAY 2017 EXTERNAL ELECTRICAL AT AFNHB SITE PREMISES(B)





EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 45%)

PROGRESS:

CIVIL FOUNDATIONS EQUIPMENT ERECTION STRUCTURE ERECTION CABLE LAYING CABLE END TERMINATION EARTHING OH LINE

- 95% completed
- Transformers, DG sets erection
- FP & TP erection
- To be done
 - To be done
 - Excavation in progress
 - -Completed