AVERAGE DAILY LABOUR IN SEP-OCT: 260



TOWER NO: A1 OFFICERS (Overall completion-92.95%)

Total floors: S1+S2+8
Total Flats: 32

PROGRESS:

STRUCTURAL WORK - 100% completed (Terrace structure completed) **BRICK WORK** - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 100% completed
PLUMBING - 100% completed
CHINA WARE FITTING - 95% completed

PAINTING - 75% (1st coat paint completed)

EXTERNAL PAINT - 80% completed
ELECTRICAL WORK - 82% completed

DOOR & WINDOW FIXING - 90% completed
FIRE FIGHTING WORK - 40% completed
CP FITTING - 85% completed

BALCONY RAILING - 100% completed

STAIRCASE RAILING - 100% completed

FALSE CEILING -100% Completed



TOWER NO: A2 OFFICERS (Overall completion-88.28%)

Total floors: S1+S2+8
Total Flats: 32


PROGRESS: STRUCTURAL WORK - 100% completed (Terrace structure)

BRICK WORK - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
- 95% completed
- 95% completed
- 80% completed

PAINTING -75% (1st coat paint completed)

EXTERNAL PAINT
-60% completed
-70% completed
-70% completed
-35% completed
-60% completed
-60% completed
-100% completed



TOWER NO: A3 OFFICERS (Overall completion-90.29%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING TILING

CHINA WARE FITTING

PAINTING

PLUMBING

-75% (1st coat paint completed)

- 95% completed - 100% completed

- 100% completed

- 70% completed

- 90% completed

- 100% completed (terrace structure completed)

- 100% completed (Except lower & upper stilt)

EXTERNAL PAINT -80% completed - 80% completed **ELECTRICAL WORK** - 60% completed **DOOR & WINDOW FIXING** FIRE FIGHTING WORK - 30% completed

BALCONY RAILING -100% completed STAIRCASE RAILING -90% completed



TOWER NO: A4 OFFICERS (Overall completion-90.80%)

Total floors: S1+S2+8
Total Flats: 32

PROGRESS:

STRUCTURAL WORK - 100% completed (Terrace structure completed)

BRICK WORK - 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING
INTERNAL PLASTERING
- 100% completed
- 90% completed

PAINTING - 75% (1st coat paint completed)

EXTERNAL PAINT

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

CP FITTING

BALCONY RAILING

-80% completed
-60% completed
-60% completed
-100% completed

BALCONY RAILING -100% completed
STAIRCASE RAILING -100% completed
FALSE CEILING -30% Completed



TOWER NO: B1 SAILOR (Overall completion-79.30%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

EXTERNAL PAINT PLUMBING

PAINTING

ELECTRICAL WORK FIRE FIGHTING WORK - 100% completed

- 95% completed

- 95% completed

- 100% completed

- 100% completed

- 80% completed

- 70% completed

- 50% (1st coat paint completed)

- 50% completed

- 15% completed



TOWER NO: B2 SAILOR (Overall completion-72.29%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING PLUMBING

PAINTING - (2nd coat putty started)

- 100% completed (Except terrace structure)

- 100% completed

- 95% completed

- 100% completed

- 80% completed - 60% completed

EXTERNAL PAINT
-80% completed
-40% completed
FIRE FIGHTING WORK
-15% completed



TOWER NO: B3 SAILOR (Overall completion-94.52%)

PLUMBING

Total floors: S1+S2+11 **Total Flats:** 42

PROGRESS:

STRUCTURAL WORK - 100% completed (Terrace structure completed)

- 100% completed **BRICK WORK EXTERNAL PLASTERING** - 100% completed **INTERNAL PLASTERING** - 100% completed **TILING** - 100% completed - 100% completed

PAINTING - 75% (1st coat paint completed)

-80% completed **EXTERNAL PAINT** - 80% completed **CHINA WIRE FITTING ELECTRICAL WORK** - 87% completed **DOOR & WINDOW FIXING** - 90% completed FIRE FIGHTING WORK - 20% completed -85% completed **CP FITTING** - 100% completed **BALCONY RAILING**

FALSE CEILING -100% Completed **STAIRCASE RAILING** -100% completed



TOWER NO: COMMUNITY CENTER (Overall completion-87%)

Total floors: G+1

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

PAINTING

ELECTRICAL WORK
FIRE FIGHTING WORK

- 100% completed (Except terrace structure)

- 90% completed

- 90% completed

- 90% completed

- (only 1st coat putty completed)

- 30% completed - 10% completed



CONNECTING SLAB (B2 & B3 BLOCK)

PROGRESS: White wash work in progress.


EXTERNAL SERVICES



UNDER GROUND RESERVOIR- (Overall completion-53.34%)

PROGRESS: Pipe line work in progress.

BOUNDARY WALL



BOUNDARY WALL- (Overall completion- 75.25%)

PROGRESS: Plastering work in progress

SWIMMING POOL



SWIMMING POOL- (Overall completion- 47%)

PROGRESS: Wall casting completed.

SWERAGE TRETMENT PLANT



SWERAGE TRETMENT PLANT (Overall completion- 53.34%)

PROGRESS: Slab casting completed.

LIFT WORK



LIFT WORK (Overall completion- 42%)

PROGRESS: 14 Nos lift material has arrived at site. And 14 nos lift work in progress all block

Lift Facia granite work completed A1 & A4 block.

EXTERNAL DRAIN WORK



EXTERNAL DRAIN WORK (Overall completion- 13%)

PROGRESS: Raft & wall casting work in progress.

FIREFIGHTING WORK



FIREFIGHTING WORK

PROGRESS: Pump installation work.

MUNICIPL PH LINE



MUNICIPAL PH LINE

PROGRESS: Completed

EXTERNAL ROAD & RETAINING WALL WORK



EXTERNAL ROAD & RETAINING WALL WORK (Overall completion- 37.28%)

PROGRESS: PCC & BDF flooring work in progress.

EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)









EXTERNAL ELECTRICAL (PART-A) - (Overall completion-89%)

PROGRESS: SP ERECTION - 100% completed

DP ERECTION - 100% completed
FP ERECTION - 100% completed
CONDUCTOR STRINGING - 100% completed
CIVIL FOUNDATIONS -100% completed

EQUIPMENT ERECTION - Transformer, VCB, Isolator, CT & PT and CR panel erected

STRUCTURE ERECTION - CT, PT, and Isolator & VCB structure erected

CABLE LAYING - 100% completed

CABLE END TERMINATION - 100% completed **EARTHING** - 100% completed **CONTROL CABLE** - 80% completed

AB CABLE -50% completed

EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)









EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 59.5%)

PROGRESS:

CIVIL FOUNDATIONS

EQUIPMENT ERECTION

STRUCTURE ERECTION

CABLE LAYING

CABLE END TERMINATION

EARTHING

OH LINE

DG FUEL ROOM

LT PANEL

LIGHTNING ARRESTOR

STREET LIGHT

TELEPHONE SYSTEM

TESTING

- 95% completed

- Transformers, DG sets erection

- FP & TP erected

- Started at officer block

- To be done

- Completed

-Completed

- Completed

- 05 nos transformer panel erected

- To be done

- Pole foundation work started

- To be done (Layout started)

-IR TEST completed