AVERAGE DAILY LABOUR IN MAR-APR: 409



TOWER NO: A1 OFFICERS (Overall completion-89.81%)

Total floors: S1+S2+8 **Total Flats:** 32

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING PLUMBING

CHINA WARE FITTING

PAINTING - 15% (1st coat paint completed)

- 95% completed

- 100% completed

- 100% completed

- 100% completed

- 95% completed

- 100% completed (terrace structure completed) - 100% completed (Except lower & upper stilt)

EXTERNAL PAINT -25% complete **ELECTRICAL WORK** - 65% completed - 90% completed **DOOR & WINDOW FIXING** FIRE FIGHTING WORK - 25% completed



TOWER NO: A2 OFFICERS (Overall completion-71.36%)

Total floors: S1+S2+8 **Total Flats:** 32

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING **PLUMBING PAINTING**

ELECTRICAL WORK

FIRE FIGHTING WORK

- 100% completed (Except terrace structure)

- 100% completed (Except lower & upper stilt)

- 80% completed - 100% completed

- 5% completed - 50% completed

- (only 1st coat putty completed)

- 35% completed

- 15% completed



TOWER NO: A3 OFFICERS (Overall completion-80.79%)

Total floors: S1+S2+8
Total Flats: 32

PROGRESS:STRUCTURAL WORK- 100% completed (Except terrace structure)BRICK WORK- 100% completed (Except lower & upper stilt)

EXTERNAL PLASTERING - 95% completed
INTERNAL PLASTERING - 100% completed
TILING - 70% completed
PLUMBING - 60% completed

PAINTING - (only 1st coat putty completed)

ELECTRICAL WORK - 35% completed
DOOR & WINDOW FIXING - 5% completed
FIRE FIGHTING WORK - 15% completed



TOWER NO: A4 OFFICERS (Overall completion-82.38%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING - 95% completed
INTERNAL PLASTERING - 100% completed
TILING/GRANITE - 100% completed
PLUMBING - 100% completed

PAINTING - 50% (2nd coat putty completed)

- 100% completed (Except terrace structure)- 100% completed (Except lower & upper stilt)

EXTERNAL PAINT -2% complete

ELECTRICAL WORK -50% completed

DOOR & WINDOW FIXING -30% completed

FIRE FIGHTING WORK -15% completed



TOWER NO: B1 SAILOR (Overall completion-63.50%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 95% completed

EXTERNAL PLASTERING - 70% completed
INTERNAL PLASTERING - 95% completed
TILING - To be done

PLUMBING - 60% completed

PAINTING - (only 1st coat putty up to 9th floor completed)

ELECTRICAL WORK - 35% completed **FIRE FIGHTING WORK** - 15% completed



TOWER NO: B2 SAILOR (Overall completion-58.24%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 90% completed

EXTERNAL PLASTERING - To be done
INTERNAL PLASTERING - 85% completed
TILING - To be done

PLUMBING - 30% completed

PAINTING - (only 1st coat putty 4th floor completed)

ELECTRICAL WORK - 25% completed FIRE FIGHTING WORK - 10% completed



TOWER NO: B3 SAILOR (Overall completion-89%)

Total floors: S1+S2+11

Total Flats: 42

PROGRESS: STRUCTURAL WORK - 100% completed (Except terrace structure)

BRICK WORK - 100% completed
EXTERNAL PLASTERING - 100% completed
INTERNAL PLASTERING - 100% completed
TILING - 95% completed
PLUMBING - 100% completed

PAINTING - 30% (1st coat paint completed)

EXTERNAL PAINT
CHINA WIRE FITTING
ELECTRICAL WORK
DOOR & WINDOW FIXING
FIRE FIGHTING WORK
-40% completed
- 80% completed
- 70% completed
- 90% completed
- 15% completed



TOWER NO: COMMUNITY CENTER (Overall completion-87%)

Total floors: G+1

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

PAINTING

ELECTRICAL WORK FIRE FIGHTING WORK - 100% completed (Except terrace structure)

- 90% completed

- 90% completed - 90% completed

- (only 1st coat putty completed)

- 30% completed - 10% completed

SEWERAGE WORK



PROGRESS: Sewerage line pipe laying work near A1 & A4 block



CONNECTING SLAB (B1 & B2 BLOCK)

PROGRESS: Stilt-2 slab casted

EXTERNAL SERVICES



UNDER GROUND RESERVOIR- (Overall completion-27.44%)

PROGRESS: Slab casted UGR-1 & 2

RETAINING WALL



RETAINING WALL- (Overall completion- 80%)

PROGRESS: Wall shuttering in progress (North side)

BOUNDARY WALL



BOUNDARY WALL- (Overall completion- 53.5%)

PROGRESS: Copping casting & clamp fixing work in progress

SWIMMING POOL



SWIMMING POOL- (Overall completion- 5%)

PROGRESS: PCC work in progress

SWERAGE TRETMENT PLANT



SWERAGE TRETMENT PLANT (Overall completion- 4%)

PROGRESS: Excavation work in progress

FIRE FIGHTING WORK



FIRE FIGHTING WORK

PROGRESS: Fire fighting ring main pipe laying for hydrant & sprinkler line near A1 block

EXTERNAL ELECTRICAL (A)





EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 70%)

PROGRESS: SP ERECTION - 100% completed

DP ERECTION - 100% completed
FP ERECTION - 100% completed
CONDUCTOR STRINGING - 100% completed
CIVIL FOUNDATIONS -100% completed

EQUIPMENT ERECTION - Transformer, VCB, Isolator, CT & PT erected **STRUCTURE ERECTION** - CT, PT, and Isolator & VCB structure erected

CABLE LAYING - 80%
CABLE END TERMINATION - 80%
EARTHING - 100%

EXTERNAL ELECTRICAL (B)







EXTERNAL ELECTRICAL (PART-B) - (Overall completion-5%)

PROGRESS:

CIVIL FOUNDATIONS - 5% completed

EQUIPMENT ERECTION - Nil (Transformers, DG sets & cable reach at site)

STRUCTURE ERECTION - Nil

CABLE LAYING - To be done

CABLE END TERMINATION - To be done

EARTHING - To be done