PROGRESS DEHRADUN AS ON 15 MAY 17 (VIEW OF PACKAGE-II)



PROGRESS DEHRADUN AS ON 15 MAY 17 (PACKAGE-II)



TOWER NO: M (overall completion 92.78%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WARE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed 98% completed (except CP fitting) -60% completed -80% completed -85% completed -95% completed --95% completed



TOWER NO: L (overall completion 93.45%)

Total Floors: - G+6

Total Flats: - 54 (1298.98 SF)

PROGRESS: STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WARE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK 100% completed
100% completed
100% completed
100% completed
100% completed
98% completed (except CP fitting)
60% completed
85% completed
92% completed
95% completed
95% completed



TOWER NO: K (overall completion 93.47%)

Total Floors: - G+6

Total Flats: - 53 (1298.98 SF)

PROGRESS: STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WARE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

100% completed
100% completed
100% completed
100% completed
100% completed
95% completed (except CP fitting)
60% completed
85% completed
92% completed
95% completed
95% completed
95% completed



TOWER NO: J (overall completion 91.35%)

Total Floors: - G+6

Total Flats: - 52 (1558.01 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 100% completed
	INTERNAL PLASTERING	- 100% completed
	TILING	- 100% completed
	PLUMBING	 95% completed (except CP fitting)
	CHINA WARE FITTING	- 10% completed
	PAINTING	- 70% completed
	ELECTRICAL WORK	- 85% completed
	DOOR & WINDOW FIXING	- 80% completed
	FIRE FIGHTING WORK	- 80% completed



<u>TOWER NO:</u> H (overall completion 85.19%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 100% completed
	INTERNAL PLASTERING	- 99% completed
	TILING	- 90% completed
	PLUMBING	 80% completed (except CP fitting)
	CHINA WARE FITTING	- 05% completed
	PAINTING	- 50% completed
	ELECTRICAL WORK	- 70% completed
	DOOR & WINDOW FIXING	- 20% completed
	FIRE FIGHTING WORK	- 50% completed



TOWER NO: G (overall completion 85.02%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 100% completed
	INTERNAL PLASTERING	- 99% completed
	TILING	- 85% completed
	PLUMBING	 60% completed (except CP fitting)
	CHINA WARE FITTING	- 05% completed
	PAINTING	- 50% completed
	ELECTRICAL WORK	- 60% completed
	DOOR & WINDOW FIXING	- 20% completed
	FIRE FIGHTING WORK	- 50% completed



TOWER NO: F (overall completion 82.23%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 99% completed
	INTERNAL PLASTERING	- 95% completed
	TILING	- 60% completed
	PLUMBING	- 60% completed (except CP fitting)
	CHINA WARE FITTING	- 05% completed
	PAINTING	- 50% completed
	ELECTRICAL WORK	- 50% completed
	DOOR & WINDOW FIXING	- 10% completed
	FIRE FIGHTING WORK	- 50% completed



TOWER NO: E (overall completion 68.12%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WARE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed
 99% completed
 95% completed
 18% completed
 Nil
 50% completed
 Nil
 15% completed
 30% completed
 Nil
- 30% completed



VIEW OF UPPER BASEMENT ROOF TOP DEVELOPMENT WORK

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

INTERNAL PLASTERING

ROADS

FIREFIGHTING

SEWER LINE

DRAIN LINE

- 100% completed
- 100% completed
- 100% completed
- 100% completed
- 75% completed
- 90% completed
- 85% completed
 - 75% completed



VIEW OF LOWER BASEMENT DEVELOPMENT WORK

PROGRESS:

(a) **LOWER BASEMENT:**

STRUCTURAL WORK INTERNAL PLASTERING VD FLOORING FIRE FIGHTING MECHANICAL VENTILATION INTERNAL ELE

- 100% completed
- 100% completed
- 100% completed
- 95% completed
- NIL
- 90% completed

(b) UPPER BASEMENT:

STRUCTURAL WORK INTERNAL PLASTERING VD FLOORING FIRE FIGHTING MECHANICAL VENTILATION INTERNAL ELE

- 100% completed
- 100% completed
- 100% completed
- 95% completed
- NIL
- 90% completed

(PACKAGE-I)



TOWER NO: A (overall completion 98.52%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed
 100% completed
 100% completed
 100% completed
 100% completed (except CP fitting)
 100% completed
 100% Completed (except final coat)
 97% completed
 95% completed
- 97% completed



TOWER NO: B (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 100% completed
	INTERNAL PLASTERING	- 100% completed
	TILING	- 100% completed
	PLUMBING	- 100% completed (except CP fitting)
	CHINA WIRE FITTING	- 100% completed
	PAINTING	 100% Completed (except final coat)
	ELECTRICAL WORK	- 97% completed
	DOOR & WINDOW FIXING	- 95% completed
	FIRE FIGHTING WORK	- 97% completed



TOWER NO: C (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed
 100% completed
 100% completed
 100% completed
 100% completed
 100% completed (except CP fitting)
 100% completed
 100% Completed (except final coat)
 97% completed
 95% completed
- 97% completed



TOWER NO: D (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: **STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING** TILING PLUMBING CHINA WIRE FITTING PAINTING **ELECTRICAL WORK** DOOR & WINDOW FIXING **FIRE FIGHTING WORK**

- 100% completed (except CP fitting) - 100% completed - 100% Completed (except final coat) - 97% completed 95% completed -
- 97% completed



TOWER NO: Q (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: - 100% completed **STRUCTURAL WORK BRICK WORK** - 100% completed **EXTERNAL PLASTERING** - 100% completed - 100% completed **INTERNAL PLASTERING** TILING - 100% completed - 100% completed (except CP fitting) PLUMBING **CHINA WIRE FITTING** - 100% completed - 100% Completed (except final coat) PAINTING **ELECTRICAL WORK** - 97% completed - 95% completed **DOOR & WINDOW FIXING** FIRE FIGHTING WORK - 97% completed



TOWER NO: P (overall completion 98.33%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed
 100% completed
 100% completed
- 100% completed
- 100% completed
- 100% completed (except CP fitting)
- 100% completed
- 100% Completed (except final coat)
- 97% completed
- 95% completed
- 97% completed



TOWER NO: N (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 100% completed
	INTERNAL PLASTERING	- 100% completed
	TILING	- 97% completed
	PLUMBING	 100% completed (except CP fitting)
	CHINA WIRE FITTING	- 100% completed
	PAINTING	- 100% Completed (except final coat)
	ELECTRICAL WORK	- 97% completed
	DOOR & WINDOW FIXING	- 95% completed
	FIRE FIGHTING WORK	- 97% completed





Progress:- Lanscapping work is on progress.