# PROGRESS DEHRADUN AS ON 15 APR 17 (VIEW OF PACKAGE-II)



# PROGRESS DEHRADUN AS ON 15 APR 17 (PACKAGE-II)



**TOWER NO:** A2B/5 (overall completion 92.76%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

**EXTERNAL PLASTERING** 

INTERNAL PLASTERING

TILING PLUMBING

**CHINA WARE FITTING** 

**PAINTING** 

ELECTRICAL WORK
DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

98% completed (except CP fitting)

- 50% completed

- 70% completed

- 85% completed

- 92% completed



#### **TOWER NO:** B2/1 (overall completion 93.45%)

Total Floors: - G+6

Total Flats: - 54 (1298.98 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING** 

INTERNAL PLASTERING

TILING

**PLUMBING** 

**CHINA WARE FITTING** 

**PAINTING** 

ELECTRICAL WORK DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 98% completed (except CP fitting)

- 60% completed

- 85% completed

90% completed95% completed



#### **TOWER NO:** B2/2 (overall completion 93.45%)

Total Floors: - G+6

Total Flats: - 53 (1298.98 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING

**INTERNAL PLASTERING** 

TILING

**PLUMBING** 

**CHINA WARE FITTING** 

**PAINTING** 

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 95% completed (except CP fitting)

- 60% completed

- 85% completed

- 90% completed

- 95% completed



TOWER NO: B1/3 (overall completion 91.32%)

Total Floors: - G+6

Total Flats: - 52 (1558.01 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING** 

INTERNAL PLASTERING

TILING

**PLUMBING** 

**CHINA WARE FITTING** 

**PAINTING** 

ELECTRICAL WORK
DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 95% completed

- 92% completed (except CP fitting)

- 05% completed

- 70% completed

- 80% completed

- 75% completed

- 80% completed



TOWER NO: B1/2 (overall completion 85.19%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS:

STRUCTURAL WORK

- 100% completed

**BRICK WORK** 

- 100% completed

- 100% completed

EXTERNAL PLASTERING

- 98% completed

INTERNAL PLASTERING TILING

- 85% completed

**PLUMBING** 

- 80% completed (except CP fitting)

**CHINA WARE FITTING** 

- 05% completed

**PAINTING** 

- 50% completed

**ELECTRICAL WORK** 

- 65% completed

DOOR & WINDOW FIXING

- 20% completed

FIRE FIGHTING WORK

- 50% completed



#### TOWER NO: B1/1 (overall completion 85.02%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING

INTERNAL PLASTERING

**TILING** 

**PLUMBING** 

**CHINA WARE FITTING** 

**PAINTING** 

ELECTRICAL WORK
DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 98% completed

- 75% completed

- 60% completed (except CP fitting)

- 05% completed

- 50% completed

- 50% completed

- 20% completed

- 50% completed



**TOWER NO:** A2B/4 (overall completion 82.23%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

**PROGRESS:** STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING** 

**INTERNAL PLASTERING TILING** 

**PLUMBING** 

**CHINA WARE FITTING** 

**PAINTING** 

**ELECTRICAL WORK DOOR & WINDOW FIXING** 

FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 98% completed

- 95% completed

- 50% completed

- 60% completed (except CP fitting)

- 05% completed

- 50% completed

- 50% completed

- 10% completed

- 50% completed



#### **TOWER NO:** A2B/3 (overall completion 68.11%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING

INTERNAL PLASTERING

**TILING** 

**PLUMBING** 

**CHINA WARE FITTING** 

DAINITINIC

**PAINTING** 

ELECTRICAL WORK

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 99% completed

- 90% completed

- 15% completed

- Nil

- 50% completed

- Nil

- 15% completed

- 30% completed

- Nil

- 30% completed









#### **VIEW OF UPPER BASEMENT ROOF TOP DEVELOPMENT WORK**

PROGRESS: STRUCTURAL WORK - 100% completed

BRICK WORK - 100% completed

**EXTERNAL PLASTERING** - 100% completed

**INTERNAL PLASTERING** - 100% completed

**ROADS** - 68% completed

**FIREFIGHTING** - 70% completed

**SEWER LINE** - 75% completed

**DRAIN LINE** - 75% completed





#### **VIEW OF LOWER BASEMENT DEVELOPMENT WORK**

#### PROGRESS:

#### (a) **LOWER BASEMENT:**

STRUCTURAL WORK - 100% completed INTERNAL PLASTERING - 100% completed VD FLOORING - 100% completed FIRE FIGHTING - 95% completed

**MECHANICAL VENTILATION** - NIL

INTERNAL ELE - 90% completed

#### (b) <u>UPPER BASEMENT:</u>

STRUCTURAL WORK - 100% completed
INTERNAL PLASTERING - 100% completed
VD FLOORING - 100% completed
FIRE FIGHTING - 90% completed

MECHANICAL VENTILATION - NIL

INTERNAL ELE - 90% completed

# PROGRESS DEHRADUN AS ON 15 APR 17 (PACKAGE-I)



**TOWER NO:** A1/1 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTU

STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING

PLUMBING

**CHINA WIRE FITTING** 

PAINTING

**ELECTRICAL WORK** 

DOOR & WINDOW FIXING FIRE FIGHTING WORK - 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed



**TOWER NO:** A1/2 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING** 

INTERNAL PLASTERING

**TILING** 

PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

ELECTRICAL WORK

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed



**TOWER NO: A1/3 (overall completion 98%)** 

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

PLUMBING CHINA WIRE FITTING

PAINTING

ELECTRICAL WORK DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

100% completed100% completed

- 100% completed

- 100% completed- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

97% completed95% completed



**TOWER NO: A1/4 (overall completion 98%)** 

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING** 

INTERNAL PLASTERING

TILING

PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

ELECTRICAL WORK
DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed



**TOWER NO:** A1/5 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

BRICK WORK

EXTERNAL PLASTERING

LATERINAL PLASTERING

**INTERNAL PLASTERING** 

**TILING** 

PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

ELECTRICAL WORK
DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

- 97% completed

- 95% completed



#### **TOWER NO:** A2/1 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

**PROGRESS: STRUCTURAL WORK** 

- 100% completed

**BRICK WORK** 

- 100% completed

- 100% completed

**EXTERNAL PLASTERING** 

- 100% completed

**INTERNAL PLASTERING** 

- 100% completed

**PLUMBING** 

**TILING** 

- 100% completed (except CP fitting)

**CHINA WIRE FITTING** 

- 100% completed

**PAINTING** 

- 100% Completed (except final coat) - 97% completed

**ELECTRICAL WORK DOOR & WINDOW FIXING** 

- 95% completed

FIRE FIGHTING WORK



**TOWER NO:** A2/2(overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING PLUMBING

CHINA WIRE FITTING

CHINA WIRE FITTING

**PAINTING** 

ELECTRICAL WORK
DOOR & WINDOW FIXING
FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed - 100% completed

- 97% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% Completed (except final coat)

97% completed95% completed





Progress:- Lanscapping work is on progress.