
### PROGRESS DEHRADUN AS ON 24 JAN 17 (PACKAGE-II)



**TOWER NO: A2B/5 (overall completion 92.28%)** 

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 96% completed

- 95% completed (except CP fitting)

- 50% completed

- 50% completed

- 80% completed

- 80% completed



TOWER NO: B2/1 (overall completion 93.23%)

Total Floors: - G+6

Total Flats: - 54 (1298.98 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING** 

**INTERNAL PLASTERING** 

**TILING** 

**PLUMBING** 

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

**DOOR & WINDOW FIXING** 

FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 98% completed

- 95% completed (except CP fitting)

- 80% completed

- 80% completed

- 90% completed

- 90% completed



# TOWER NO: B2/2 (overall completion 93.25%)

Total Floors: - G+6

Total Flats: - 53 (1298.98 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

**PLUMBING** 

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 98% completed

- 95% completed (except CP fitting)

- 80% completed

- 80% completed

- 90% completed

- 90% completed



**TOWER NO: B1/3 (overall completion 89.51%)** 

Total Floors: - G+6

Total Flats: - 52 (1558.01 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING INTERNAL PLASTERING

**TILING** 

**PLUMBING** 

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 85% completed

- 90% completed (except CP fitting)

- 05% completed

- 60% completed

- 70% completed

- 60% completed



TOWER NO: B1/2 (overall completion 82.24%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK - 100% completed

- 100% completed

- 95% completed

- 90% completed

- 80% completed

- 60% completed (except CP fitting)

- 05% completed

- 50% completed

- 50% completed

- 20% completed



**TOWER NO: B1/1 (overall completion 79.27%)** 

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

PLUMBING

CHINA WIRE FITTING

**PAINTING** 

**ELECTRICAL WORK** 

DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 90% completed

- 90% completed

- 50% completed

- 50% completed (except CP fitting)

- 05% completed

- 50% completed

- 40% completed

- 20% completed



TOWER NO: A2B/4 (overall completion 77.79%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

ELECTRICAL WORK

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 95% completed

- 90% completed

- 90% completed

- 10% completed

- 50% completed (except CP fitting)

- 05% completed

- 50% completed

- 50% completed

- 10% completed



**TOWER NO: A2B/3 (overall completion 64.48%)** 

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING INTERNAL PLASTERING** 

**TILING** 

**PLUMBING** 

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

**DOOR & WINDOW FIXING** 

FIRE FIGHTING WORK

- 96% completed

- 90% completed

- 50% completed

- 10% completed

- Nil

- 40% completed

- Nil

- 10% completed

- 30% completed

- Nil

- 30% completed

This is the only Tower which is lagging behind. Therefore maximum force and manpower is being deployed in this tower. Concerted effort will bring up this tower at par with others.









# **VIEW OF UPPER BASEMENT ROOF TOP DEVELOPMENT WORK**

PROGRESS:

STRUCTURAL WORK **BRICK WORK EXTERNAL PLASTERING** INTERNAL PLASTERING **ROADS FIREFIGHTING SEWER LINE** 

DRAIN LINE

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 50% completed

- 40% completed

- 50% completed





### **VIEW OF LOWER BASEMENT DEVELOPMENT WORK**

#### **PROGRESS:**

# (a) **LOWER BASEMENT:**

STRUCTURAL WORK
INTERNAL PLASTERING
VD FLOORING
FIRE FIGHTING
- 100% completed
- 70% completed
- 75% completed

**MECHANICAL VENTILATION** - NIL

INTERNAL ELE - 90% completed

#### (b) <u>UPPER BASEMENT:</u>

STRUCTURAL WORK
INTERNAL PLASTERING
VD FLOORING
FIRE FIGHTING
- 100% completed
- 100% completed
- 100% completed
- 90% completed

**MECHANICAL VENTILATION** - NIL

INTERNAL ELE - 90% completed

### PROGRESS DEHRADUN AS ON 24 JAN 17 (PACKAGE-I)

**Important:** Considering the progress of contractor of Package-I has been given Go Ahead to complete the balance works, including finishing work in each DU and construction of Guard etc so as to complete work of package I in all respect by 31 Mar 2017



**TOWER NO:** A1/1 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING** 

**INTERNAL PLASTERING** 

TILING **PLUMBING** 

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

**DOOR & WINDOW FIXING** FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% completed (except final coat)

- 97% completed

- 95% completed



**TOWER NO:** A1/2 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

ELECTRICAL WORK
DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed


- 100% completed (except CP fitting)

- 100% completed

- 100% completed (except final coat)

- 97% completed

- 95% completed



TOWER NO: A1/3 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING

**INTERNAL PLASTERING** 

TILING PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% completed (except final coat)

- 97% completed

- 95% completed



**TOWER NO:** A1/4 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

**EXTERNAL PLASTERING INTERNAL PLASTERING** 

**TILING PLUMBING** 

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

**DOOR & WINDOW FIXING** FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% completed (except final coat)

- 97% completed

- 95% completed



# **TOWER NO:** A1/5 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING

INTERNAL PLASTERING

TILING PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

ELECTRICAL WORK
DOOR & WINDOW FIXING

FIRE FIGHTING WORK

- 100% completed


- 100% completed (except CP fitting)

- 100% completed

- 100% completed (except final coat)

- 97% completed

- 95% completed



**TOWER NO: A2/1 (overall completion 98%)** 

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING

**PLUMBING** 

**CHINA WIRE FITTING** 

**PAINTING** 

ELECTRICAL WORK

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% completed (except final coat)

- 97% completed

- 95% completed



#### **TOWER NO:** A2/2(overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK

**BRICK WORK** 

EXTERNAL PLASTERING INTERNAL PLASTERING

TILING PLUMBING

**CHINA WIRE FITTING** 

**PAINTING** 

**ELECTRICAL WORK** 

DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed

- 100% completed

- 100% completed

- 100% completed

- 97% completed

- 100% completed (except CP fitting)

- 100% completed

- 100% completed (except final coat)

- 97% completed

- 95% completed