# PROGRESS DEHRADUN AS ON 08 MAR 17 (VIEW OF PACKAGE-II)



## PROGRESS DEHRADUN AS ON 08 MAR 17 (PACKAGE-II)



#### TOWER NO: A2B/5 (overall completion 92.76%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

#### PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK - 100% completed 98% completed (except CP fitting) -50% completed -- 60% completed 80% completed -92% completed -85% completed -



#### TOWER NO: B2/1 (overall completion 93.29%)

Total Floors: - G+6

Total Flats: - 54 (1298.98 SF)

PROGRESS: STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK 100% completed
100% completed
100% completed
100% completed
100% completed
98% completed (except CP fitting)
60% completed
85% completed
90% completed
90% completed
95% completed



#### TOWER NO: B2/2 (overall completion 93.30%)

Total Floors: - G+6

Total Flats: - 53 (1298.98 SF)

PROGRESS: STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK 100% completed
100% completed
100% completed
100% completed
100% completed
95% completed (except CP fitting)
60% completed
85% completed
90% completed
90% completed
95% completed
95% completed



### TOWER NO: B1/3 (overall completion 90.61%)

Total Floors: - G+6

Total Flats: - 52 (1558.01 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 100% completed
	INTERNAL PLASTERING	- 100% completed
	TILING	- 90% completed
	PLUMBING	<ul> <li>92% completed (except CP fitting)</li> </ul>
	CHINA WIRE FITTING	- 05% completed
	PAINTING	- 60% completed
	ELECTRICAL WORK	- 75% completed
	DOOR & WINDOW FIXING	- 70% completed
	FIRE FIGHTING WORK	- 80% completed



### TOWER NO: B1/2 (overall completion 83.53%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 100% completed
	INTERNAL PLASTERING	- 97% completed
	TILING	- 85% completed
	PLUMBING	<ul> <li>70% completed (except CP fitting)</li> </ul>
	CHINA WIRE FITTING	- 05% completed
	PAINTING	- 50% completed
	ELECTRICAL WORK	- 55% completed
	DOOR & WINDOW FIXING	- 20% completed
	FIRE FIGHTING WORK	- 50% completed



### TOWER NO: B1/1 (overall completion 81.73%)

Total Floors: - G+6

Total Flats: - 54 (1558.01 SF)

	100% consulated
STRUCTURAL WORK	- 100% completed
BRICK WORK	- 100% completed
EXTERNAL PLASTERING	- 100% completed
INTERNAL PLASTERING	- 95% completed
TILING	- 65% completed
PLUMBING	<ul> <li>50% completed (except CP fitting)</li> </ul>
CHINA WIRE FITTING	- 05% completed
PAINTING	- 50% completed
ELECTRICAL WORK	- 50% completed
DOOR & WINDOW FIXING	- 20% completed
FIRE FIGHTING WORK	- 50% completed
	EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING



### TOWER NO: A2B/4 (overall completion 79.44%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 98% completed
	INTERNAL PLASTERING	- 92% completed
	TILING	- 30% completed
	PLUMBING	- 50% completed (except CP fitting)
	CHINA WIRE FITTING	- 05% completed
	PAINTING	- 50% completed
	ELECTRICAL WORK	- 50% completed
	DOOR & WINDOW FIXING	- 10% completed
	FIRE FIGHTING WORK	- 50% completed



TOWER NO: A2B/3 (overall completion 66.50%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

#### PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK 100% completed
98% completed
85% completed
10% completed
Nil
40% completed
Nil
15% completed
30% completed
Nil
30% completed



#### VIEW OF UPPER BASEMENT ROOF TOP DEVELOPMENT WORK

- PROGRESS: STRUCTURAL WORK
  - BRICK WORK
  - EXTERNAL PLASTERING
  - INTERNAL PLASTERING
  - ROADS
  - FIREFIGHTING
  - SEWER LINE
  - **DRAIN LINE**

- 100% completed
- 100% completed
- 100% completed
- 100% completed
- 68% completed
- 64% completed
- 65% completed
- 62% completed





#### VIEW OF LOWER BASEMENT DEVELOPMENT WORK

#### PROGRESS:

(a) **LOWER BASEMENT:** 

STRUCTURAL WORK INTERNAL PLASTERING VD FLOORING FIRE FIGHTING MECHANICAL VENTILATION INTERNAL ELE

#### (b) UPPER BASEMENT:

STRUCTURAL WORK INTERNAL PLASTERING VD FLOORING FIRE FIGHTING MECHANICAL VENTILATION INTERNAL ELE

- 100% completed
- 100% completed
- 70% completed
- 85% completed
- NIL
- 90% completed
- 100% completed
- 100% completed
- 100% completed
- 90% completed
- NIL
- 90% completed

# PROGRESS DEHRADUN AS ON 08 MAR 17 (PACKAGE-I)



#### TOWER NO: A1/1 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

#### PROGRESS:

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK 100% completed
100% completed
100% completed
100% completed
100% completed (except CP fitting)
100% completed
100% Completed (except final coat)
97% completed
95% completed
97% completed
97% completed



#### TOWER NO: A1/2 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

**PROGRESS: STRUCTURAL WORK** - 100% completed **BRICK WORK** - 100% completed **EXTERNAL PLASTERING** - 100% completed - 100% completed **INTERNAL PLASTERING** - 100% completed TILING - 100% completed (except CP fitting) PLUMBING **CHINA WIRE FITTING** - 100% completed PAINTING - 100% Completed (except final coat) - 97% completed **ELECTRICAL WORK** - 95% completed DOOR & WINDOW FIXING FIRE FIGHTING WORK - 97% completed



#### TOWER NO: A1/3 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

#### **PROGRESS:**

STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK 100% completed
100% completed
100% completed
100% completed
100% completed (except CP fitting)
100% completed
100% Completed (except final coat)
97% completed
95% completed
97% completed
97% completed



### TOWER NO: A1/4 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS:	STRUCTURAL WORK	- 100% completed
	BRICK WORK	- 100% completed
	EXTERNAL PLASTERING	- 100% completed
	INTERNAL PLASTERING	- 100% completed
	TILING	- 100% completed
	PLUMBING	- 100% completed (except CP fitting)
	CHINA WIRE FITTING	- 100% completed
	PAINTING	- 100% Completed (except final coat)
	ELECTRICAL WORK	- 97% completed
	DOOR & WINDOW FIXING	- 95% completed
	FIRE FIGHTING WORK	- 97% completed



TOWER NO: A1/5 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (2321.74 SF)

PROGRESS: STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK 100% completed
100% completed
100% completed
100% completed
100% completed
100% completed (except CP fitting)
100% completed
100% Completed (except final coat)
97% completed
95% completed
97% completed
97% completed



#### TOWER NO: A2/1 (overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: **STRUCTURAL WORK** - 100% completed **BRICK WORK** - 100% completed - 100% completed **EXTERNAL PLASTERING INTERNAL PLASTERING** - 100% completed TILING - 100% completed - 100% completed (except CP fitting) PLUMBING - 100% completed **CHINA WIRE FITTING** PAINTING - 100% Completed (except final coat) - 97% completed **ELECTRICAL WORK** DOOR & WINDOW FIXING - 95% completed FIRE FIGHTING WORK - 97% completed



#### TOWER NO: A2/2(overall completion 98%)

Total Floors: - G+6

Total Flats: - 54 (1951 SF)

PROGRESS: STRUCTURAL WORK BRICK WORK EXTERNAL PLASTERING INTERNAL PLASTERING TILING PLUMBING CHINA WIRE FITTING PAINTING ELECTRICAL WORK DOOR & WINDOW FIXING FIRE FIGHTING WORK

- 100% completed
  100% completed
  100% completed
  100% completed
  97% completed
  100% completed (except CP fitting)
  100% completed
  100% Completed (except final coat)
  97% completed
  95% completed
- 97% completed





Progress:- Lanscapping work is on progress.