



PANORAMIC VIEW OF AFNHB JALANDHAR PROJECT



A1 & A2 BLOCKS-(overall completion 96%)

Total Floors: - Stilt +9

Total Flats: - 106 (1351 SFT EACH)

PROGRESS:External painting, minor repairs/rectifications works of electric wiring, aluminium of , testing of electrical/plumbing work in progress. Work services for meter panel rooms and balance of flooring in the stilts in progress.



B1- BLOCK (overall completion 98%)

Total Floors: - Stilt +8

Total Flats: - 48 (955.0 SFT)

PROGRESS: All work completed ready for handing over, Housekeeping and maintenance in progress.



<u>COMMUNITY CENTER</u> (overall completion 99%)

PROGRESS: All work completed ready for handing over, housekeeping and maintenance in progress.



INSIDE VIEW OF COMMUNITY CENTRE.





Basement Parking- Progress 99% (House keeping in Progress)





VIEW OF MAIN ENTRANCE GATE

WORK IN PROGRESS (labour camps in front of site removed)



LANDSCAPING WORK IN PROGRESS

PROGRESS JALANDHAR AS ON 30 OCT 2016



VIEW OF SWIMMING POLL



INTERNAL ROAD WORK IN FINISHING STAGE

PROGRESS JALANDHAR AS ON 30 OCT 2016



ELECTRICAL SUB STATION

SUBSTATION ENERGIZED