



FIXING OF SHUTTER AT ELECTRICAL SHAFT



FIXING OF SHUTTER AT PLUMBING SHAFT

TOWER-1 (TYPE A-1) (Overall completion 92.25 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – Repairing of Vitrified tiles, OBD in Flats.





FIXING OF KOTA STONE AT PODIUM



CC FLOORING IN MACHINE ROOM

TOWER 2 (TYPE A-1) (Overall completion 80.0 %)

Total Floor – Stilt + 10

Total flat = 60

Progress –Fixing of Aluminum frames in windows, fixing of Vitrified tiles in bed rooms, Fixing of Green marble in staircase, CC flooring in machine room, wall tiles in Kitchen & External primer in progress.



TOWER-3 (TYPE A-1) (Overall completion 68.80 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – External Plaster and external primer, fixing of vitrified tiles in rooms, wall tile in WCs, casting slabs of machine room.



TOWER-4 (TYPE A-1) (Overall completion 65.50 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – Pressure testing of PPR pipes, External plaster and Fixing of door frames, fixing of marble in corridors.





FIXING OF RAILING OF STAIRCASE



EXTERNAL PLASTER

TOWER-5 (TYPE A-2) (Overall completion 75.0 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – Brick work around OH water tank, Railing fixing of Staircase External plaster of common areas.





OBD IN FLAT



WHITE WASH AT STILT FLOOR

TOWER-6 (TYPE A-2) (Overall completion 88.00 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – White wash at stilt floor & OBD in flat at 1st floor, PCC of stilt floor.



TOWER-7 (TYPE B-1) (Overall completion 89.00 %)

Total Floor – Stilt + 11

Total flat = 119

Progress – Plaster repairing at stilt floor, Fixing of wall tile of WCs.





ALUMINIUM WORK



FIXING OF VITRIFIED TILES IN BALCONY

TOWER- 8 (TYPE B-1 & TYPE B2) (Overall completion 88.50 %)

Total Floor – Stilt + 11

Total flat = 33+33

Progress – Fixing of main frame of aluminium in widows & Internal OBD Ist coat, fixing of vitrified tiles in balcony.





CC FLOORING IN GYMNASIUM

COMMUNITY CENTRE - (Overall completion 92.00 %)

Total floor – Basement +03

Progress - CC flooring in Gymnasium fixing of wooden molding on door frames.



FACILITY BLOCK - (Overall completion 95.15 %)

Total floor – Ground +01

Progress – No progress.





VISITOR'S ROOM



GATE 1

SWIMMING POOL



MAIN DRIVE IN


Gate No. 1 - (Overall completion 90.00 %)

Progress – Road work in progress 20%, Reinf. Steel binding of raft of Swimming pool.



STP - (Overall completion 37.26 %)

Progress – Further progress on approval from MDA.



Power House - (Overall completion 96.00 %)

Progress – Generators, transformers, HT/LT cables and control panels procured, Awaiting Energising & Laying of pipe in road crossing, Excavation for Earthning pits.