

TOWER-1 (TYPE A-1) (Overall completion 91.85 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – Fixing of false ceiling in toilets, Glass fixing in Aluminum windows & ventilators, Internal Painting, Repairing of Ext plaster and Fixing of Fire Doors etc.



TOWER 2 (TYPE A-1) (Overall completion 78.40 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – Fixing of Vitrified tiles in bed rooms, Green marble in corridor at 10<sup>th</sup>, floor, Kota stone flooring in corridor, water proofing in toilets wall tiles in Kitchen & toilets, brick coba at terrace floor. External primer in progress.



TOWER-3 (TYPE A-1) (Overall completion 67.20 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – External & Internal plaster, Fixing of door frame & Fixing of wall tiles in toilets & kitchen, Green marble in corridor, Plumbing works, RCC works in terrace, Water proofing toilets & kitchen ,Kota stone in corridor and podium etc.



TOWER-4 (TYPE A-1) (Overall completion Approx 65%)

Total Floor – Stilt + 10

Total flat = 60

Progress – External & Internal plastering, RCC works in terrace, Fixing of Doors frame, Fixing of Aluminum frame, Water proofing in toilet & Kitchen, Plumbing works, Fixing of grills in corridor etc.



TOWER-5 (TYPE A-2) (Overall completion 73.00 %)

Total Floor – Stilt + 10

Total flat = 60

Progress – External plaster of flat 1, Fixing of Green marble in corridor at 4<sup>rd</sup> floor, Fixing of Kota stone at podium, Shuttering of wall of OH water tank, POP cornice in bed rooms etc



TOWER-6 (TYPE A-2) (Overall completion 86.10%)

Total Floor – Stilt + 10

Total flat = 60

Progress – Internal painting in flats at 7th floor, fixing of false ceiling in toilets, Grinding of Kota stone of podium Fixing of glass in aluminum windows etc.



TOWER-7 (TYPE B-1) (Overall completion 87.70 %)

Total Floor – Stilt + 11

Total flat = 119

Progress – Floor and wall tiles fixing, Granite fixing in Kitchen plat form, Aluminum frame fixing in windows, Brick work of Garbage room at stilt floor, Preparation of stilt for PCC.



TOWER- 8 (TYPE B-1 & TYPE B2) (Overall completion 87.30 %)

Total Floor – Stilt + 11

Total flat = 33.

Progress – Fixing of main frame of aluminium in widows & Internal Paiting , White wash at stilt floor etc.





FIXING OF KOTA STONE AT STAIRCASE



WATER PROOFING OF SWIMMING POOL

#### COMMUNITY CENTRE - (Overall completion 92.00 %)

Total floor – Basement +03

**Progress – Fixing of Kota stone at staircase towards of swimming pool.** 



FACILITY BLOCK - (Overall completion 95.15 %)

Total floor – Ground +01

**Progress – Internal OBD Ist coat & painting on Staircase railing.** 















Gate No. 1 - (Overall completion 90.00 %)

Progress – Road work in progress 11.00% & Fixing of Kota stone in Visitor's Room.



STP - (Overall completion 37.26 %)

Civil work completed in 2013, No progress in electro mechanical works, excepted to commence by Sep 2017



SUB Station - (Overall completion 96.00 %)

Progress – Generators, Transformers installed in 2013, HT/LT cables and control panels procured, Servecing of DG stes and Tranformers initiated, Fixinf of feedar piller near Tower 1& 6.