

TOWER 1 (TYPE A-1)(Overall completion 92.50%)

Total Floor – Stilt + 10

Total flat = 60

Progress: STRUCTURE WORK 100% COMPLETED BRICK WORK 100% COMPLETED BALCONY & CORRIDOR RAILING 100% COMPLETED STAIRCASE RAILING 100% COMPLETED INTERNAL PLASTER 100% COMPLETED EXTERNAL PLASTER 100% COMPLETED PLUMBING WORK 90% COMPLETED **TILING & MARBLE 100% COMPLETED DOOR WINDOW 75% COMPLETED INTERNAL PAINTING 70% COMPLETED EXTERNAL PAINTING 55% COMPLETED FALSE CEILLING 100% COMPLETED ELECTRICAL WORK 75% COMPLETED FIRE FIGHTING WORK 65% COMPLETED CHINAWARE FITTING 90% COMPLETED CP FITTINGS** NIL



TOWER 2 (TYPE A-1)(Overall completion 81.00%)

Total Floor – Stilt + 10 Total flat = 60

Progress: STRUCTURE WORK **BRICK WORK BALCONY & CORRIDOR RAILING** STAIRCASE RAILING **INTERNAL PLASTER EXTERNAL PLASTER PLUMBING WORK TILING & MARBLE DOOR WINDOW INTERNAL PAINTING EXTERNAL PAINTING** FALSE CEILLING NIL **ELECTRICAL WORK FIRE FIGHTING WORK CHINAWARE FITTING** NIL **CP FITTINGS** NIL

100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 75% COMPLETED 80% COMPLETED 20% COMPLETED 15% COMPLETED NIL 50% COMPLETED 50% COMPLETED NIL NIL



TOWER 3 (TYPE A-1) (Overall completion 69.00%)

Total Floor – Stilt + 10

Total flat = 60

Progress:	STRUCTURE WORK	95% COMPLETED
	BRICK WORK	90% COMPLETED
	BALCONY & CORRIDOR RAILING	90% COMPLETED
	STAIRCASE RAILING	95% COMPLETED
	INTERNAL PLASTER	95% COMPLETED
	EXTERNAL PLASTER	65% COMPLETED
	PLUMBING WORK	50% COMPLETED
	TILING & MARBLE	15% COMPLETED
	DOOR WINDOW	20% COMPLETED
	INTERNAL PAINTING	10% COMPLETED
	EXTERNAL PAINTING	5% COMPLETED
	FALSE CEILLING	NIL
	ELECTRICAL WORK	40% COMPLETED
	FIRE FIGHTING WORK	50% COMPLETED
	CHINAWARE FITTING	NIL
	CP FITTINGS	NIL



TOWER 4 (TYPE A-1) (Overall completion 70.00%)

Total Floor – Stilt + 10 Total flat = 60

Progress: STRUCTURE WORK 90% COMPLETED 90% COMPLETED BRICK WORK BALCONY & CORRIDOR RAILING 90% COMPLETED STAIRCASE RAILING **95% COMPLETED INTERNAL PLASTER 70% COMPLETED EXTERNAL PLASTER 50% COMPLETED** PLUMBING WORK **40% COMPLETED TILING & MARBLE 10% COMPLETED DOOR WINDOW 15% COMPLETED INTERNAL PAINTING** NIL **EXTERNAL PAINTING 5% COMPLETED FALSE CEILLING** NIL **ELECTRICAL WORK 40% COMPLETED** FIRE FIGHTING WORK **50% COMPLETED CHINAWARE FITTING** NIL **CP FITTINGS** NIL



TOWER 5 (TYPE A-2)(Overall completion 76.00%)

Total Floor – Stilt + 10 Total flat = 60

Progress: STRUCTURE WORK 100% COMPLETED 100% COMPLETED BRICK WORK BALCONY & CORRIDOR RAILING 100% COMPLETED STAIRCASE RAILING **100% COMPLETED INTERNAL PLASTER 100% COMPLETED EXTERNAL PLASTER** 95% COMPLETED PLUMBING WORK **70% COMPLETED TILING & MARBLE 25% COMPLETED** DOOR WINDOW **30% COMPLETED INTERNAL PAINTING 15% COMPLETED EXTERNAL PAINTING 10% COMPLETED** FALSE CEILLING NIL **ELECTRICAL WORK 40% COMPLETED** FIRE FIGHTING WORK **50% COMPLETED CHINAWARE FITTING** NIL **CP FITTINGS** NIL



TOWER 6 (TYPE A-2) (Overall completion 88.50%)

Total Floor – Stilt + 10

Total flat = 60

Progress: **STRUCTURE WORK 100% COMPLETED BRICK WORK 100% COMPLETED BALCONY & CORRIDOR RAILING 100% COMPLETED 100% COMPLETED** STAIRCASE RAILING **100% COMPLETED INTERNAL PLASTER EXTERNAL PLASTER 100% COMPLETED PLUMBING WORK 90% COMPLETED TILING & MARBLE 95% COMPLETED DOOR WINDOW 70% COMPLETED INTERNAL PAINTING 70% COMPLETED EXTERNAL PAINTING 45% COMPLETED FALSE CEILLING 80% COMPLETED ELECTRICAL WORK 75% COMPLETED** FIRE FIGHTING WORK **65% COMPLETED 50% COMPLETED CHINAWARE FITTING CP FITTINGS** NIL



TOWER 7 (TYPE B-1)(Overall completion 89.50%)

Total Floor – Stilt + 11 Total flat = 119

Progress:

STRUCTURE WORK BRICK WORK BALCONY & CORRIDOR RAILING STAIRCASE RAILING INTERNAL PLASTER EXTERNAL PLASTER PLUMBING WORK TILING & MARBLE DOOR WINDOW INTERNAL PAINTING EXTERNAL PAINTING FALSE CEILLING **ELECTRICAL WORK FIRE FIGHTING WORK CHINAWARE FITTING CP FITTINGS**

100% COMPLETED 98% COMPLETED 98% COMPLETED 95% COMPLETED 100% COMPLETED 100% COMPLETED 75% COMPLETED 70% COMPLETED 55% COMPLETED 30% COMPLETED 15% COMPLETED NIL **50% COMPLETED 60% COMPLETED** NIL NIL



TOWER 8 (TYPE B-1 & TYPE B2) (Overall completion 89.00%)

Total Floor – Stilt + 11

Total flat = 33.

Progress:

STRUCTURE WORK BRICK WORK BALCONY & CORRIDOR RAILING STAIRCASE RAILING **INTERNAL PLASTER EXTERNAL PLASTER** PLUMBING WORK **TILING & MARBLE** DOOR WINDOW **INTERNAL PAINTING EXTERNAL PAINTING** FALSE CEILLING **ELECTRICAL WORK FIRE FIGHTING WORK** CHINAWARE FITTING **CP FITTINGS**

100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 80% COMPLETED 20% COMPLETED 75% COMPLETED 60% COMPLETED 15% COMPLETED NIL **60% COMPLETED 60% COMPLETED 60% COMPLETED** NIL



Total floor – Basement +03

Progress:

STRUCTURE WORK BRICK WORK BALCONY & CORRIDOR RAILING STAIRCASE RAILING INTERNAL PLASTER EXTERNAL PLASTER PLUMBING WORK TILING & MARBLE DOOR WINDOW **INTERNAL PAINTING EXTERNAL PAINTING FALSE CEILLING ELECTRICAL WORK FIRE FIGHTING WORK CHINAWARE FITTING CP FITTINGS**

100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 75% COMPLETED 100% COMPLETED 95% COMPLETED 35% COMPLETED 75% COMPLETED 50% COMPLETED 80% COMPLETED 65% COMPLETED 80% COMPLETED NIL



Total floor – Ground +01

Progress:

STRUCTURE WORK BRICK WORK STAIRCASE RAILING INTERNAL PLASTER EXTERNAL PLASTER PLUMBING WORK TILING & MARBLE DOOR WINDOW INTERNAL PAINTING EXTERNAL PAINTING ELECTRICAL WORK FIRE FIGHTING WORK CP FITTINGS 100% COMPLETED 100% COMPLETED 100% COMPLETED 100% COMPLETED 90% COMPLETED 90% COMPLETED 95% COMPLETED 75% COMPLETED 75% COMPLETED 90% COMPLETED 90% COMPLETED



MAIN GATE & BOUNDARY WALL - 70 % WORK IS COMPLETED





ROAD WORK - WBM IN PROGRESS NEAR BLOCK 1,6,7& 8

PROGRESS: 20 % COMPLETED



STP
STRUCTURE
WATER PROOFING OF WALL
BRICK WORK & PLASTER OF MUMTY
WATER PROOFING OF TOP SLAB

37 % COMPLETED 100 % COMPLETED 100% COMPLETED 100% COMPLETED IN PROGRESS



SWIMMING POOL

PCC OF BASE

REINFORCEMENT STEEL BINDING OF RAFT & WALL

20% COMPLETED

65% COMPLETED 65 % COMPLETED



Power house - (Overall completion 96.00 %)

<u>Progress:</u> Generators, transformers, HT/LT cables and control panels procured, Awaiting Energising & Installation of Feader Pillars near Tower 1& 6.