

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

AVERAGE DAILY LABOUR IN JAN 2017- FEB 2018: 245



TOWER NO: A1 OFFICERS (Overall completion-95.45%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS:

| | |
|---------------------------------|--|
| STRUCTURAL WORK | - 100% completed (Terrace structure completed) |
| BRICK WORK | - 100% completed (Except lower & upper stilt) |
| EXTERNAL PLASTERING | - 100% completed |
| INTERNAL PLASTERING | - 100% completed |
| TILING | - 100% completed |
| PLUMBING | - 100% completed |
| CHINA WARE FITTING | - 95% completed |
| PAINTING (INTERNAL) | - 100% (1st coat paint completed) |
| EXTERNAL PAINT | - 80% completed |
| ELECTRICAL WORK | - 92% completed |
| DOOR & WINDOW FIXING | - 90% completed |
| FIRE FIGHTING WORK | - 50% completed |
| CP FITTING | - 85% completed |
| BALCONY RAILING | - 100% completed |
| STAIRCASE RAILING | - 100% completed |
| FALSE CEILING | -100% Completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018



TOWER NO: A2 OFFICERS (Overall completion-92.15%)

Total floors: S1+S2+8

Total Flats: 32

PROGRESS:

| | |
|---------------------------------|---|
| STRUCTURAL WORK | - 100% completed (Terrace structure) |
| BRICK WORK | - 100% completed (Except lower & upper stilt) |
| EXTERNAL PLASTERING | - 100% completed |
| INTERNAL PLASTERING | - 100% completed |
| TILING | - 100% completed |
| PLUMBING | - 80% completed |
| PAINTING | -100% (1st coat paint completed) |
| EXTERNAL PAINT | -80% completed |
| ELECTRICAL WORK | - 85% completed |
| FIRE FIGHTING WORK | - 50% completed |
| DOOR & WINDOW FIXING | - 60% completed |
| BALCONY RAILING | -100% completed |
| CHINA WARE FITTING | - 90% completed |
| STAIRCASE RAILING | - 100% completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018



TOWER NO: A3 OFFICERS (Overall completion-93.05%)

Total floors: S1+S2+8

Total Flats: 32

| | | |
|-------------------------|---------------------------------|--|
| <u>PROGRESS:</u> | STRUCTURAL WORK | - 100% completed (terrace structure completed) |
| | BRICK WORK | - 100% completed (Except lower & upper stilt) |
| | EXTERNAL PLASTERING | - 100% completed |
| | INTERNAL PLASTERING | - 100% completed |
| | TILING | - 100% completed |
| | PLUMBING | - 90% completed |
| | CHINA WARE FITTING | - 90% completed |
| | PAINTING | -100% (1st coat paint completed) |
| | EXTERNAL PAINT | -80% completed |
| | ELECTRICAL WORK | - 85% completed |
| | DOOR & WINDOW FIXING | - 60% completed |
| | FIRE FIGHTING WORK | - 50% completed |
| | BALCONY RAILING | -100% completed |
| | STAIRCASE RAILING | -100% completed |
| | FALSE CEILING | -70% Completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018



TOWER NO: A4 OFFICERS (Overall completion-94.04%)

Total floors: S1+S2+8

Total Flats: 32

| | | |
|-------------------------|---------------------------------|--|
| <u>PROGRESS:</u> | STRUCTURAL WORK | - 100% completed (Terrace structure completed) |
| | BRICK WORK | - 100% completed (Except lower & upper stilt) |
| | EXTERNAL PLASTERING | - 100% completed |
| | INTERNAL PLASTERING | - 100% completed |
| | TILING/GRANITE | - 100% completed |
| | PLUMBING | - 100% completed |
| | CHINA WARE FITTING | - 90% completed |
| | PAINTING | -100% (1 st coat paint completed) |
| | EXTERNAL PAINT | -80% completed |
| | ELECTRICAL WORK | - 85% completed |
| | DOOR & WINDOW FIXING | - 60% completed |
| | FIRE FIGHTING WORK | - 50% completed |
| | CP FITTING | -60% completed |
| | BALCONY RAILING | -100% completed |
| | STAIRCASE RAILING | -100% completed |
| | FALSE CEILING | -90% Completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018



TOWER NO: B1 SAILOR (Overall completion-88.85%)

Total floors: S1+S2+11

Total Flats: 43

| | | |
|-------------------------|---------------------------------|----------------------------------|
| <u>PROGRESS:</u> | STRUCTURAL WORK | - 100% completed |
| | BRICK WORK | - 100% completed |
| | EXTERNAL PLASTERING | - 100% completed |
| | INTERNAL PLASTERING | - 100% completed |
| | TILING | - 100% completed |
| | EXTERNAL PAINT | - 90% completed |
| | PLUMBING | - 80% completed |
| | PAINTING | -100% (1st coat paint completed) |
| | ELECTRICAL WORK | - 80% completed |
| | FIRE FIGHTING WORK | - 50% completed |
| | DOOR & WINDOW FIXING | - 50% completed |
| | CHINA WARE FITTING | - 90% completed |
| | FALSE CEILING | -100% Completed |
| | BALCONY RAILING | -100% completed |
| | STAIRCASE RAILING | -10% completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018



TOWER NO: B2 SAILOR (Overall completion-84.86%)

Total floors: S1+S2+11

Total Flats: 43

PROGRESS:

| | |
|---------------------------------|---|
| STRUCTURAL WORK | - 100% completed (Except terrace structure) |
| BRICK WORK | - 100% completed |
| EXTERNAL PLASTERING | - 100% completed |
| INTERNAL PLASTERING | - 100% completed |
| TILING | - 95% completed |
| PLUMBING | - 80% completed |
| PAINTING | - 100% (1st coat paint completed) |
| EXTERNAL PAINT | -85% completed |
| ELECTRICAL WORK | - 62% completed |
| FIRE FIGHTING WORK | - 45% completed |
| DOOR & WINDOW FIXING | - 40% completed |
| BALCONY RAILING | -100% completed |
| STAIRCASE RAILING | -10% completed |
| FALSE CEILING | -50% Completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018



TOWER NO: B3 SAILOR (Overall completion-96.84%)

Total floors: S1+S2+11

Total Flats: 42

PROGRESS:

| | |
|---------------------------------|--|
| STRUCTURAL WORK | - 100% completed (Terrace structure completed) |
| BRICK WORK | - 100% completed |
| EXTERNAL PLASTERING | - 100% completed |
| INTERNAL PLASTERING | - 100% completed |
| TILING | - 100% completed |
| PLUMBING | - 100% completed |
| PAINTING | - 100% (1st coat paint completed) |
| EXTERNAL PAINT | - 80% completed |
| CHINA WIRE FITTING | - 80% completed |
| ELECTRICAL WORK | - 87% completed |
| DOOR & WINDOW FIXING | - 100% completed |
| FIRE FIGHTING WORK | - 45% completed |
| CP FITTING | - 85% completed |
| BALCONY RAILING | - 100% completed |
| FALSE CEILING | - 100% Completed |
| STAIRCASE RAILING | - 100% completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018



TOWER NO: COMMUNITY CENTER (Overall completion-89.45%)

Total floors: G+1

PROGRESS:

| | |
|---------------------------------|--|
| STRUCTURAL WORK | - 100% completed (Except terrace structure) |
| BRICK WORK | - 90% completed |
| EXTERNAL PLASTERING | - 100% completed |
| INTERNAL PLASTERING | - 100% completed |
| PAINTING | - 60% (1 st coat putty completed) |
| ELECTRICAL WORK | - 50% completed |
| FIRE FIGHTING WORK | - 30% completed |
| DOOR & WINDOW FIXING | - 30% completed |
| BALCONY RAILING | - 100% completed |
| EXTERNAL PAINT | - 80% completed |
| TILING | - 40% completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

SWIMMING POOL



SWIMMING POOL- (Overall completion- 53%)

PROGRESS: Balancing tank tiling work completed & Accessories reached at site.

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

LIFT WORK



LIFT WORK (Overall completion- 70%)

PROGRESS: 14 Nos lift material has arrived at site. And 10 nos lift work in progress all block

Lift commissioning completed A1 , A4 & B1 block.

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

EXTERNAL DRAIN WORK



EXTERNAL DRAIN WORK (Overall completion- 75%)

PROGRESS: Raft & Wall casting work in progress.

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

FIREFIGHTING WORK



FIREFIGHTING WORK

PROGRESS: Sprinkler painting.

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

EXTERNAL ROAD & RETAINING WALL WORK



EXTERNAL ROAD & RETAINING WALL WORK (Overall completion- 65%)

PROGRESS: PCC & VDF flooring work in progress.

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

RECHARGE PIT



RECHARGE PIT (Overall completion- 65%)

PROGRESS: Cover casting work in progress.

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

EXTERNAL ELECTRICAL WORK AT CESU PREMISES (A)



CABLE TRENCH COVERING IN SIDE AFNHB



CABLE END TERMINATION IN SIDE AFNHB



EXTERNAL ELECTRICAL (PART-A) - (Overall completion- 90%)

PROGRESS:

| | |
|-----------------------|--|
| SP ERECTION | - 100% completed |
| DP ERECTION | - 100% completed |
| FP ERECTION | - 100% completed |
| CONDUCTOR STRINGING | - 100% completed |
| CIVIL FOUNDATIONS | -100% completed |
| EQUIPMENT ERECTION | - Transformer, VCB, Isolator, CT & PT and CR panel erected |
| STRUCTURE ERECTION | - CT, PT, and Isolator & VCB structure erected |
| CABLE LAYING | - 100% completed |
| CABLE END TERMINATION | - 100% completed |
| EARTHING | - 100% completed |
| CONTROL CABLE | - 100% completed |
| AB CABLE | -90% completed |

PROGRESS BHUBANESWAR AS ON 15 FEB 2018

EXTERNAL ELECTRICAL WORK AT AFNHB SITE PREMISES (B)




**CABLE LAYING FROM TRF TO
PANEL AT S/S-2**



**CABLE LAYING FROM TRF TO
PANEL AT S/S-1**



**LT CABLE LAYING FOR
OFFICER BLOCK**



**LIGHTNING ARRESTER
WORK AT OFFICER BLOCK**

EXTERNAL ELECTRICAL (PART-B) - (Overall completion- 72%)

PROGRESS:

| | |
|------------------------------|--|
| CIVIL FOUNDATIONS | - 95% completed |
| EQUIPMENT ERECTION | - Transformers, DG sets erected |
| STRUCTURE ERECTION | - FP & TP erected |
| CABLE LAYING | - 75% completed |
| CABLE END TERMINATION | - Started at officers block |
| EARTHING | - Completed |
| OH LINE | - Completed |
| DG FUEL ROOM | - Completed |
| LT PANEL | - 05 nos transformer panel erected |
| LIGHTNING ARRESTOR | - Earthing of officers block completed (A2, A3 & A4 BLOCK) |
| STREET LIGHT | - Pole foundation work started |
| TELEPHONE SYSTEM | - HDPE pipe laying work in progress |
| TESTING | - IR TEST completed |