

WEB UPDATE JALANDHAR AS ON 28 OCT 15

Progress Status of Towers :

Tower – A : Finishing work in progress like brick work, internal electric work, Fixing of Doors, Windows, Granite in common Area, Sanitary Fittings, CP Fittings, Final Coat of OBD.
Over all Progress – 69%

Tower B : Finishing work in progress like, Internal Plaster, External Plaster, Internal conducting, fixing of door/ windows, wall & Floor, tiling work, Marble / Granite work, Fixing of Sanitary Fitting.

Over all Progress – 86%

Lifts : The order for procurement of lift material has been placed by the contractor.

External Works :

Basement Work : Excavation of basement, brick & plastering work in progress, Ramp slab casting in Progress.

Photograph Attached.

Boundary Wall : Excavation & foundation 85% completed, Brick work & plastering 55% completed.

Photograph Attached.

Water Tank / Pump Room : Excavation work completed, Raft casting in progress, RCC wall work is in progress 97%.

Photograph Attached.

External Electrical : LT Panels procured, Transformer procurement in Progress