

Progress Of Greater Mohali As On 18 May 17

Tower ‘A’
Work completed in Totality



Total No of DUs = 39

No. of DUs Handed over = 39

Common Area including lift and Fireworks =

Common Area not yet taken over.
Lifts taken over.
Firemain line-functional

Status
Touching up of paint in common Area is pending. Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'B'
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 51

Common Area including lift and Fire works = Common Area not yet taken over.
Lifts taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending. Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘C’
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 51

Common Area including lift and Fire works =

Common Area not yet taken over.

Lifts taken over.

Firemain line-functional

Status

Touching up of paint in common Area is pending.

Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'D'
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 50

(Only One DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area and Lifts taken over.

Firemain line-functional

Status

Fire fighting Equipments & accessories locked in the shafts and in custody of the society .

.

Progress Of Greater Mohali As On 18 May 17

Tower ‘E’
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 48

(Only three DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area and lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is **completed**. Fire fighting Equipments & accessories in the custody of the contractor

.

Progress Of Greater Mohali As On 18 May 17

Tower 'F'
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 50

(Only one DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is completed . Fire fighting Equipments & accessories in the custody of the contractor

.

Progress Of Greater Mohali As On 18 May 17

Tower ‘G’
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 50
(Only one DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status
Touching up of paint in common Area is completed . Fire fighting Equipments & accessories in the custody of the contractor .

Progress Of Greater Mohali As On 18 May 17

Tower ‘H’
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 47

(Four DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody

Progress Of Greater Mohali As On 18 May 17

Tower ‘I’
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 49

(Only two DU is yet to be taken over by allottee)
Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘J’

Work completed in Totality



Total No of DUs = 40

No. of DUs Handed over = 30

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘K’
Work completed in Totality



Total No of DUs = 42

No. of DUs Handed over = 26

(Only **Sixteen** DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'L'
Work completed in Totality



Total No of DUs = 55

No. of DUs Handed over = 50

(Only **Five** DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the
custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'M'

Work completed in Totality



Total No of DUs = 42

No. of DUs Handed over = 36

(Only Six DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.

Firemain line-functional

Status

Touching up of paint in common Area is pending.

Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'N'
Work completed in Totality



Total No of DUs = 42

No. of DUs Handed over = 33

(Only nine DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'O'
Work completed in Totality



Total No of DUs = 40

No. of DUs Handed over = 21

(Only **Nineteen** DU is yet to be taken over by allottee)

ommon Area including lift and Fire works = Common Area & Lifts not yet taken over.

Firemain line-functional

Status

Touching up of paint in common Area is pending.

Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'P'
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 49

(Only **two** DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'Q'
Work completed in Totality



Total No of DUs = 53

No. of DUs Handed over = 51

(Only two DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.

Firemain line-functional

Status

Touching up of paint in common Area is pending.

Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘R’
Work completed in Totality



Total No of DUs = 54

No. of DUs Handed over = 46

(Only eight DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'S'
Work completed in Totality



Total No of DUs = 54

No. of DUs Handed over = 48

(Only six DU is yet to be taken over by allottee)
Common Area including lift and Fire works = Common Area & Lifts not yet taken over.

Firemain line-functional

Status

Touching up of paint in common Area is pending.

Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘T’
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 45

(Only six DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the
custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘U’
Work completed in Totality



Total No of DUs = 51

No. of DUs Handed over = 47

(Only four DU is yet to be taken over by allottee)
Common Area including lift and Fire works = Common Area & Lifts not yet taken over.

Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the
custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'V'

Work completed in Totality



Total No of DUs = 54

No. of DUs Handed over = 46

(Only **eight** DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.

Firemain line-functional

Status

Touching up of paint in common Area is pending.

Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘W’

Work completed in Totality



Total No of DUs = 54

No. of DUs Handed over = 48

(Only six DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower 'X'
Work completed in Totality



Total No of DUs = 54

No. of DUs Handed over = 49

(Only five DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘Y’
Work completed in Totality



Total No of DUs = 54

No. of DUs Handed over = 43

(Only **Eleven** DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is pending.
Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Tower ‘Z’
Work completed in Totality



Total No of DUs = 54

No. of DUs Handed over = 41

(Only Thirteen DU is yet to be taken over by allottee)

Common Area including lift and Fire works = Common Area & Lifts not yet taken over.
Firemain line-functional

Status

Touching up of paint in common Area is in progress. Fire fighting Equipments & accessories in the custody of the contractor

Progress Of Greater Mohali As On 18 May 17

Clock Tower
Work completed in Totality



Clock Tower . The Clock is mounted with GPS and is fully functional. **The clock Tower is in the custody of JVT Society.**

Progress Of Greater Mohali As On 18 May 17

Landscaping **Work completed in Totality**



Arboriculture & Irrigation System: To improve greenery, approximately 160 ornamental & flowering plants have been planted along the boundary wall. To enhance the grace of the boundary wall further , about 300 Bouganvillea plants have been planted . In addition about 700 shrubs, creepers have been planted in the central lawn and more such plants are being planned to be planted to fill the gaps. The controller unit for the irrigation system has been installed. The irrigation system in the central lawn and boundary wall are operational.

Swimming Pool of package I

Swimming Pool of package I has been handed over to the society. The JVT residents can make use of the pool in the coming summer, once the safety measures are instituted by the Society.

Swimming pool and Community Centre II.

The Swimming pool and CCII have been taken over by the JVT Society.

Additional Work

At the request of the JVT Society, AFNHB has undertaken additional work like passage lights for basement, SS gates to passage from towers to basement, increase the height of boundary wall near Tower K & L, fitment of fibre sheet at the boundary wall to stop the stray dogs in campus etc.